Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR STATES BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF	LAND MANAGEMENT nen	5. Lease Designation and Serial No.
	LAND MANAGEMENT	** NM_100831
	AND REPORTS ON WELLS	VED 6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to di		ក្តែអ៊ូ teserម្តីម៉ូរ៉េ
USE APPLICATION FO	R PERMIT-" for such proposals	
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
	IN TRIPLICATE	1808
1. Type of Well Oil X Gas Well Duher		8. Well Name and No.
2. Name of Operator		
YATES PETROLEUM CORPORATION	(505) 748-1471	Bat ARO Federal #1
3. Address and Telephone No.		30-015-25874
105 South 4th St., Artesia, NM 88210		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Crooked Creek Morrow
2210' FNL & 660' FWL of Section 34-T23S-R24E (Unit E, SWNW)		
		Eddy Co., NM
12. CHECK APPROPRIATE BOX	S) TO INDICATE NATURE OF NO	OTICE, REPORT, OR OTHER DATA
	T	
TYPE OF SUBMISSION	T	PE OF ACTION
Notice of Intent	Abandonment !	Change of Plans
Also Also Also Also Also Also Also Also	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
n	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Spud on re	Dispose Water (Note: Report results of multiple completion on Well
13. Describe Proposed or Completed Operation (Clarity)		Completion or Percompletion Report and Londown
give subsurface locations and measured and true verti	in pertinent details, and give pertinent dates, including e cal depths for all markers and zones pertinent to this s	stimated date of starting any proposed work. If well is directionally drilled work.)*
		ig out cellar and welded on startin
head. Installed cellar. Dig working pit, set and test anchors. Moved in and rigged up		
pulling unit and reverse unit equipment. Nippled up tubinghead and 5K BOP and tested.		
Shut down.		
12-2-98 - Rigged up $4-3/4$ " bit, collar and swivel and spudded in at 7:00 AM $12-1-98$.		
Drilled on surface plug. Drilled 260' of cement. Pulled up and circulated hole clean.		
Shut down overnight.		. And may
		at 475'. TIH and tagged cement
hole clean. Shut down overni		70 . Ficked up and directiated
	_	at 2675' TIH with tubing and
12-4-98 - Continue drilling cement. Fell out of cement at 2675'. TIH with tubing and tagged up at 7941'. Drilled 8' of cement. Tagged CIBP at 7949'. Circulate well clean.		
Shut down overnight.	or compact rapper orbi	de //// Cilculate well clean
	7949'. TIH with tubing ar	nd tagged RBP at 8505' (no cement
on top of RBP). TOOH with tu	bing, drill collars and bit	. TIH with bit, scraper and tubing
		packer and tubing. Set packer at
7917' and tested to 1000 psi.		
12-6-98 Swabbed. Shut well		
14. I hereby centry that the horegoing as you and correction	Well in overnight.	
Signed Sustantilla	Title Operations Techn	nician Dec. 7, 1998
(This space for Federal or State office use)		Date
Approved by	Title	Date