Ferm 3160=5 (November 1983) (Formerly 9-331)

UN. ED STATES DEPARTMENT OF THE INTERIOR (Other Instructions verse side) (2210

SUBMIT IN TRIPLICATE. Instructions

Form approved. Budget Bureau No. 1004-013

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM 19842-B

7. UNIT AGREEMENT NAME

ı	Expires August 31, 1985	
1	5. LEASE DESIGNATION AND SERIAL	NO

SUNDRY NOTICES AND REPORTS ON WI	ELLS
(No not use this form for proposals to drill or to deepen or plug back to a (Use "APPLICATION FOR PERMIT—" for such proposals.)	different reservoir.
• • • • • • • • • • • • • • • • • • • •	2000

KECEIVED

BUREAU OF LAND MANAGEMENT

NAME OF OPERATOR

Santa Fe Energy Operating Partners, L.P.

DEC 18'89

500 W. Illinois, Suite 500, Midland, Texas 79701 O.C.D. togarms or well (Report location clearly and in accordance with any State requirementalia, OFFICE Sec also space 17 below.) At surface

1780' FNL & 330' FEL, Sec. 34, T-22S, R-28E

15 ELEVATIONS (Show whether DF, RT, GR, etc.)

API #30-015-26010

14. PERMIT NO.

3068' GR

8. FARM OR LEASE NAME N. E. Loving 34 Federal 9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

E. Herradura Bend Delaware 11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA

Sec. 34, T-22S, R-28E 12 COUNTY OR PARISH | 13. STATE Eddy

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT OFF FRACTURE TREAT SHOOT OR ACHIZE		FULL OR ALTER CASING MULTIPLE COMPLETE ABANDON®	XX	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING		ALTERING CASING ABANDONMENT*	
(Other)	<u>:</u> !	CHANGE PLANS		(Other) (Note: Report res Completion or Reco	ults of multiple piapletion Report	completion on Wall	

South, Proposed on Computation of English State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Procedure verbally approved by Mr. Shannon Shaw on Nov. 29, 1989.

MIRU Baber Well Service.

Set CIBP at ±3600'.

Perf 4-1/2" csg at 500' w/ cmt squeeze holes.

RIH w/ tbg. Load hole w/ 9.5# salt gel mud.

Set 50' cmt plugs: on CIBP at 3600', across salt base at 2450', and above salt top at ± 1100 ' (salt top est. at ± 1300 ').

Set 4-1/2" cmt retainer at ± 431 '.

Sting into retainer w/ tbg. Circ cement to surface through squeeze perfs at 500'.

Pull out of retainer and place 35' cement on retainer.

Set 50' surface cement plug.

Cut off wellhead 5' below GL and set dry hole marker.

This work will begin on December 5, 1989.

 \bigcirc . ::: <u>:</u> :

I hereby cerdify that the foregoing is true and correct TITLE Sr. Production Clerk (This space for Pederal or State office use)

APPROVED BY: CONDITIONS OF APPROVAL, IF ANY:

DATE 13-13 87