

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 19842-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

N. E. Loving 34 Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

E. Herradura Bend Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 34, T-22S, R-28E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ SANTA FE SNYDER CORP.

2. NAME OF OPERATOR

Santa Fe Energy Operating Partners, L.P.

3. ADDRESS OF OPERATOR

500 W. Illinois, Suite 500, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1780' FNL and 330' FEL, Sec. 34, T-22S, R-28E

14. PERMIT NO.

API # 30-015-26010

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3068' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

12-8-89: RIH w/ Alpha 12,000 psi CIBP and set at 3600'. RU 3-1/8" casing squeeze gun and shot 2 squeeze perfs at 500'. Pump 50' cmt plug from 3600'-3550' (all plugs Cl. "H" mixed 15.6# w/yield of 1.18 cu.ft/sk and 5.2 gal/sk). Spotted 50' plug from 2450'-2400'. Spotted 50' plug from 1100'-1050'. PU Howco EZ Drill cmt retainer and set retainer at 431'. Pumped 28-1/2 bbl cmt to surface thru squeeze perfs. Spot 50' cmt plug to surface in 4-1/2" csg.

12-9-89: Cleaned location. Dug out cellar 5' w/ backhoe. Welder cut off 8-5/8" csg and welded marker on casing. Cleaned and covered cellar and location. Well P&A'd.

Post ID-2  
12-15-89  
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Sr. Production Clerk

DATE 12-11-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side