Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I	OIL CONSERVATION	N DIVISION	
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		30-015-26034	
DISTRICT III			5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTI	CES AND REPORTS ON WE	LLSpecewen	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PEUGEBACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well:	,	FEB 27 '89	
WELL X	OTHER	110 27 03	Mule Foot 5 State Com
2. Name of Operator Santa Fe Energy Opera	ting Partners I P	O. C. D.	8. Well No.
3. Address of Operator	ting farthers, L.F.	ARTESIA, OFFICE	0.00
500 W. Illinois, Suite 500, Midland, TX 79701  4. Well Location			9. Mool name or Wildcat  Baldridge Canyon Morrow
Unit Letter <u>C</u> : 198	O Feet From The West	Line and 990	Feet From The North Line
Section 5	Township 24S R	ange 25E	NMPM Eddy
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	NMPM County
11. Check Appropriate Box to Indicate Noture of Nation B.			
NOTICE OF INTERVENIENCE DAY to indicate Nature of Nonce, Report, or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
2-2-89: TD 11,160', hole size 8 3/4", set 8 cmt plugs			
1st plug @ 10,905-10,765' - 50 sx PS Lite H & 4% thrad & 3# 11.5 cal			
2nd plug @ 10,308-10,168' - 50 sx H Neat			
3rd plug @ 8,184- 8,044' - 50 sx H Neat 4th plug @ 6,155- 6,015' - 50 sx H Neat			
5th plug @ 4,162- 4,022' - 50 sx H Neat			
6th plug @ 3,294- 3,181' - 75 sx H Neat			
7th plug @ 406- 270' - 50 sx H Neat .			
8th plug @ 60' to Surface - 20 sx H Neat  Set dry hole marker, cleaned location.  Released rig @ 8 PM 2-3-80  3-3-89			
Set dry hole marker, cleaned location. Released rig @ 8 PM 2-3-89			3-3-89
Released fig	e o rm 2-3-89		PYP
			• • • • • • • • • • • • • • • • • • • •
I hereby certify that the information above is true a	and complete to the best of much and do at		
Billio Dlag of			
SIGNATUREX	TITL	Sr. Production	1 Clerk 2-23-89 915/
TYPEOR PRINT NAME Billie Hood			TELEPHONE NO. 687-3551
(This space for State Use)			
APPROVED BY Davil Moore TIME Suclagist 8/18/89			
CONDITIONS OF APPROVAL, IF ANY:			