

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

State	BLM
Land Office	
B of M	
Operator	

Form C-101
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26130
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name COQUINA
8. Well No. 1
9. Pool name or Wildcat UND, HERRADURA BEND CHERRY CANYON
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3044.7GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐ JUL 28 '89

2. Name of Operator
NEEF OIL AND GAS

3. Address of Operator
150 WASHINGTON AVE., SUITE 200 SANTA FE, N.M. 87504

4. Well Location
Unit Letter C : 990 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 29 Township 22S Range 28E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUGGED AND ABANDONED WELL AS FOLLOWS:

Set Type HM CIBP @3250' Circulated hole with gelled water mixed @25#/bbl.

PLUG #1: 3250' w/25sx Class "C" +2% Tagged @ 2215' in 2 hours
PLUG #2: 2200' w/25sx Class "C" +2% Tagged @1832' in 2 1/4 hours
PLUG #3: 1150' w/25sx Class "C" +2% Tagged @768' in 2 hours
PLUG #4: 449' w/25sx Class "C" +2% Tagged @ 80' in 2 hours
PLUG #5: 50' w/15sx Class "C" Circulated 10sx to pit

Removed well head and installed regulation dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE AGENT DATE 7-20-89
TYPE OR PRINT NAME GENE LEE TELEPHONE NO. 622-7355

(This space for State Use)

APPROVED BY Danell Moore TITLE Geologist DATE 11/3/89
CONTINUOUS APPROVAL BY ANY: