Submit 3 Copies to Appropriate

State of New Mexico E

	ა	iale or	IACM IATO	MU	
nergy,	Minerals	and Na	atural Re	esources	Department

inta Fe	V	
B.M		
Land Office		
B of M	\mathbf{L}	
Operator	\mathbf{Z}	<u> </u>
WELL API NO	_	 •

Form C·103 Revised 1-1-89

District Office		•	B of M			
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI	Operator WELL API NO.				
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088			30-015-26151			
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE					
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.					
SUNDRY NOTION OF THE SUNDRY NO	7. Lease Name or Unit Agreement Name					
I. Type of Well: OR GAS WELL XX WELL	отнеж	AUG 04 '89	RGA			
2. Name of Operator		O. C. D.	8. Well No.			
Bird Creek Resou	rces, Inc.	ARTESIA, OFFICE	9. Pool name or Wildcat			
Address of Operator	W-1-1	- 70701				
1110 N. Big Spri Well Location	ng Midland, Texa	S /9/01	Undesignated			
Unit Letter K: 208	0 Feet From The South	Line and 2180	Feet From The West Line			
Section 14	Township 23 S	Range 28 E	NMPM Eddy County			
	10. Elevation (Show wheth	her DF, RKB, RT, GR, etc.)				
	3003.2'	 				
•	Appropriate Box to Indicat					
NOTICE OF INT	TENTION TO:	SUE	SEQUENT REPORT OF:			
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING			
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT			
ULL OR ALTER CASING	EMENT JOB X					
OTHER:		OTHER:				
	tions (Clearly state all pertinent details	s, and give pertinent dates, inclu	uding estimated date of starting any proposed			
=	•	ateralog, Comp	pensated Neutron Density,			
3-1-89 Ran 6,250'	GR, Caliper. Ran 6,250' 5½" 15.5# J-55 LTC casing w/DV tool @ 2,989'. 1st Stage: 1,065 sx H-Poz 50/50, 0.4%CF-2, 5# salt,2% gel, 0.3% TF-4					
		5# salt, 0.2%	CF-14			
	Open tool,	surface.				
2nd St	-		15# salt, 6% gel, 4# Cello-			
	sea 50 sx Cla		2. Circ 125 sx to surface.			
	50 sx Cla @ 5AM. Float OK.	ass C, 2% CaCl2				
8-2-89 Plug down	50 sx Cla @ 5AM. Float OK. tion Unit.	Released rig (
8-2-89 Plug down WO complet	50 sx Cla @ 5AM. Float OK. tion Unit.	Released rig (

(This space for State Use)

OIL AND GAS INSPECTOR

AUG 0 8 1989

.