

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-26205
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VA-804

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter N : 990 Feet From The South Line and 1880 Feet From The West Line

Section 36 Township 23S Range 23E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4333.7' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Re-entry ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-31-96 - Cleaned location and dig working pit. Set and tested anchors. Moved in and rigged up pulling unit. Moved in reverse unit equipment. Nipped up BOP.
1-1-2-97 - TIH with bit and collar. TIH and tagged 1st plug at 10'. Spudded in at 9:00 AM 12-31-96. Rigged up swivel and drilled 10' of cement. TIH with bit and collars. Tagged 2nd cement plug at 177'. Drilled out plug and cement from 177' to 425'. Fell out of cement at 425'. TIH and tagged 3rd cement plug at 2313'. Rigged up swivel and drilled 10'. Picked up and circulated hole clean. Shut down for New Years.
1-3-97 - Picked up swivel and tagged cement at 2323'. Fell out of cement at 2500'. TIH and well kicked. Circulated gas out. Tagged 4th cement plug at 5206'. Drilled out plug and cement to 5350'. TIH and tagged 5th cement plug at 7468'. Drilled out cement and plug to 7582'. Circulated for 1 hour. TIH and tagged 6th plug at 9030'. Circulated gas out for 2 hours. Drilled out cement and plug to 9160'. Circulated well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Jan. 3, 1997

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE JAN 8 1997

CONDITIONS OF APPROVAL, IF ANY: