Submit 3 Copies to Appropriate District Office

Ene

DIMIC OF LICH INTEVIOU Minerals and Natural Resources Departmer Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICTIII

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

CONFIDENTIAL

	וי
ELL API NO.	
30-015-26213	
5. Indicate Type of Lease STATE	· FEE X
SIAIE	I LL LAJ

1000 Rio Brazos Rd., Azteo	, NM 87410	OOM IDL	,)	6. State Oil & Gas Lease No.	
(DO NOT USE THIS FO	ORM FOR PROPOSA	AND REPORTS ON VALS TO DRILL OR TO DEEL USE "APPLICATION FOR	PEN OR RECCEBAS TO A	7. Lease Name or Unit Agreement Name	
		OR SUCH PROPOSALS.)			
1. Type of Well: OIL WELL X	GAS WELL	OTHER	DEC 4'89	South Culebra Bluff 23	
2. Name of Operator		/	C	8. Well No.	
RB Opera 3. Address of Operator	ting Company	<u>/</u>	ARTESIA OFFICE	2	
· -	Grandview Su	uite 201, Odessa,	Texas 79761	9. Pool name or Wildcat	
4. Well Location	oranaview, or	title 201, Odessa,	1exas /9/01	E. Loving (Delaware)	
Unit LetterL	: 1920 F	ect From The South	Line and 66	O Feet From The West Line	
Section	23 T	ownship 23-S	Range 28-E	NMPM Eddy County	
		///	ther DF, RKB, RT, GR, etc.); 3019.7 RKB		
11.	Check Appr	opriate Box to Indica	ite Nature of Notice, R	eport, or Other Data	
NOTIC	CE OF INTENT	TION TO:	SUE	SEQUENT REPORT OF:	
PERFORM REMEDIAL W	ORK .	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDO	N \square	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING			CASING TEST AND C	EMENT JOB	
OTHER:	·- · · · · · · · · · · · · · · · · · ·		OTHER: Perforat	ed and fraced Delaware FormationX	
12. Describe Proposed or C work) SEE RULE 1103	ompleted Operations (6 3.	Clearly state all pertinent detai	ls, and give pertinent dates, inclu	ding estimated date of starting any proposed	
T.D. 6310	', PBTD 6292'				
11-24-89 11-25-89	100 gallons 7-1/2% Nefe balls, swep K.B.	7-1/2 Nefe, HCL, HCL w/ 50 ball st perforations,	across perforationsealers. Treated circulated packer	, 2 SPF. Spotted 100 gallons ns. Acidized w/ 1000 gallons 3.2 BPM @ 1300#, surged off fluid. Set packer at 6024'	
11 23 37	20/40 sand 15 mins. 80	+ 6250# 16/30 Wes 0#. SI 6-1/2 hor	stprop. AIR 18 BP	M at 4000#. ISIP 900#, to frac tanks, in 3 days	
I hereby certify that the inform	nation above is true and co	mplete to the best of my Knowledg	e and belief.		
SIGNATURE	01	X	- ππε <u>Area Manager</u>	DATE 11-30-89	
	F. D. Schoch			362-6302 ТЕЦЕРНЮНЕ НО(915)	
	ORIGINAL SIGN				
	MIKE WILLAMS		TT(1 P	DEC - 7 1989	