

Santa Fe	
BLM	
Land Office	
Is of TA	
Operator	

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-20-204

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

SIDEWINDER

8. Well No.

1

9. Pool name or Wildcat

SEEPING BENDS

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

YATES ENERGY CORPORATION

3. Address of Operator

P.O. Box 2323 Roswell, NM 88202

4. Well Location

Unit Letter F : 2310 Feet From The NORTH Line and 1980 Feet From The WEST Line

Section

20

Township

24-S

Range

24-E

NMPM

EDDY

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4277.6

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 50 sxs. class "C" cement plug or 100' (which ever is greater) from 2900-2800'.
- Spot 50sxs. class "C" cement plug or 100'(which ever is greater) from 2525-2425' and TAG.
Cut off 5 1/2" casing @ 2000' & pull same.
- Spot 60 sxs. class "C" cement plug or 100' (which ever is greater) from 2050-1950' and TAG.
- Spot 100' class "C" cement plug across 13 3/8" shoe from 350-250' & TAG
OR bring cement up to surface.
- If cement is not circulated to surface set 10 sxs. min. of cement at suface and erect dry hole marker.

Corrects
per 1B6A
10/18/96

*

Plugging mud consisting of 10# brine with 25# of gel per barrel between all plug
NOTIFY OCD IN SUFFICIENT TIME TO WITNESS TAGS ON PLUGS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

TYPE OR PRINT NAME

MARK ROSS

505-623-4435 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

OIL AND GAS INSPECTOR

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 18 1996