

PLUG AND ABANDON AS FOLLOWS " *DR* 11/1/90

10-28-90      Plug I - 35 sx Class H 12,010-11,860'  
                 Plug II - 35 sx Class H 10,550-10,400'

10-29-90      Tag Plug II at 10,209', witnessed by NMOCD  
                 Plug III - 35 sx Class H 9325-9200'  
                 Cut & pull 6250', 7", 23#, S-95 casing

10-30-90      Plug IV - 50 sx Class H 6315-6105'  
                 Tag Plug IV at 6105', witnessed by NMOCD  
                 Plug V - 50 sx Class H 5810-5700'  
                 Plug VI - 50 sx Class H 2314-2037'  
                 Tag Plug IV at 1987', witnessed by NMOCD  
                 Plug VII - 50 sx Class H 602-467'

10-31-90      Plug VIII - 12 sx Class H 12-3'  
                 Weld on 1/2" plate on 13-3/8" casing stub &  
                 install dry hole marker.

Note: Mud laden fluid was placed between all plugs.