

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED

Bureau No. 1004-0135

Expires: March 31, 1993

CIFK

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

5. Lease Designation and Serial No.

NM-29233

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

8. Well Name and Number

GETTY 24 FEDERAL

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

4

3. Address and Telephone No.

205 E. Bender, HOBBS, NM 88240

397-0405

9. API Well No.

30-015-26482

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The

10. Field and Pool, Exploratory Area
LIVINGSTON RIDGE DELAWARE

WEST Line Section 24 Township 22S Range 31E

11. County or Parish, State

EDDY, NEW MEXICO

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

TYPE OF ACTION

Notice of Intent

☒ Subsequent Report

Final Abandonment Notice

Abandonment

Recompletion

Plugging Back

Casing Repair

Attaching Casing

☒ OTHER: PERF/ACIDIZE & FRAC

Change of Plans

New Construction

Non-Routine Fracturing

Water Shut-Off

Conversion to Injection

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-06-00: MIRU. TIH W/PARAFFIN KNIFE ON RDS. CUT 1100-3750'.

11-07-00: NDWH. NUBOP.

11-08-00: TIH W/BIT, DC'S ON WS. STOP BIT @ 2370'.

11-09-00: PU WS. TAG @ 7396' PULL BIT TO 6770'.

11-13-00: MIRU FOAM UNIT. BREAK CIRC @ 6770'. TIH W/BIT & TAG @ 7400'. C/O SAND TO 7430'. TAG CIBP @ 7430'. DRILL TO 7450'.

11-14-00: LOWER BIT & TAG @ 7450'. DRILL OUT FORMATION SAND TO 8230'.

11-15-00: TAG FILL @ 8150'. C/O SAND FILL TO PBTD @ 8368'.

11-16-00: TIH W/PERF GUN & PERF 7698-7706, 7840-7848, 7940-12, 8244-8264. TIH W/FRAC PKR & SN ON TBG. TEST TO 8000#. STOP @ 4280.

11-17-00: TIH W/TBG & TEST TO 8000#. SET PKR @ 8182'. ACIDIZE BRUSHY CANYON PERFS 8244-64' W/2000 GALS 15% NEFE HCL.

11-20-00: RU SWAB. FL @ SURF. END FL @ 7800. SWAB ADRY.

11-21-00: FL @ 6900'. END FL @ 7900'. FRAC BRUSHY CANYON PERFS 8244-64' W/14,784 GALS 25# X-LINK GEL.

11-29-00: TIH W/COILED TBG W/WASH TIP. TAG SAND @ 4000'. C/O FRAC SAND TO 8232'.

12-01-00: TIH W/FP. TBG FREE @ PKR. TIH W/CHEM CUTTER & CUT TBG @ 8170'. TIH W/OS, BMPR SUB. JARS.

12-04-00: TIH W/TBG & TOOLS. TAG @ 8170'. LATCH ON FSH. JAR LOOSE. TIH W/RBP & PKR. STOP TOOLS @ 3860'.

12-05-00: SET RBP @ 8004'. SET PKR @ 7990'. TEST RBP TO 500#-OK. SET PKR @ 7583'. ACIDIZE DELAWARE PERFS 7698-7912 W/2500 GALS 15% NEFE.

12-06-00: UNSET PKR & LOWER TO 7882. TAG SALT FILL. FILL ABOVE RBP. TIH W/RET TOOL TO 6600'. PULL FOAM UNIT.

12-07-00: TAG @ 7851'. C/O TO RBP @ 8002'. REL RBP. TIH W/MILL & DC'S ON TBG. MILL @ 3300'.

12-08-00: LOWER TOOLS TO 6700'. TAG FILL @ 8258'. C/O 8258-8370.

12-11-00: TAG @ 8355'. TIH W/PURGE VALVE. SN. TBG. TAG. STOP @ 6003'.

ACCEPTED FOR RECORD

FEB 27 2001

14. I hereby certify that the foregoing is true and correct.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

TYPE OR PRINT NAME J. Denise Leake

DATE

1/23/01

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.