Submit 3 Copies

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

State of New Mexico Energy, Minerals and Natural Resources Department

RECEIVE)
---------	---

d	5/	1
3	Vo	1
-89	- 1	

to Appropriate District Office

OIL CONSERVATION DIVISION P.O. Box 2088

O. C. D.	-
VELL AM No. A. CFF: 03 30-015-26613	
5. Indicate Type of Lease	<u></u>

DISTRICT II Santa Fe, New Mexico 87504-2088		30-015-26613			
P.O. Drawer DD	, Artesia, NM 88210		0 0/304 2000	5. Indicate Type of Lease STATE XX FEE	
	Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
	SUNDRY NOTIC	ES AND REPORTS ON WI	ELLC	G-575 & NM-VB-193	777.
(DO NOT USE	E THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEPE	ELLO EN OR PLUG RACK TO A		
	DIFFERENT RESERVI	OIR. USE "APPLICATION FOR P D1) FOR SUCH PROPOSALS.)	ERMIT"	7. Lease Name or Unit Agreement Name	
1. Type of Well	:			1	
MET	WEIL X	OTHER		Lamb Chop 17 State Com	
2. Name of Ope Santa F		ing Partners, L.P.		8. Well No.	
3. Address of O	perator	and restricted Dist.		9. Pool name or Wildcat	
550 W.	Texas, Suite 13	30, Midland, Texas	79701	Und. (Strawn) Gas	
4 Meli Pocenios	1				
Unit Let	ner <u>0</u> : 660	Feet From The South	Line and23	East East	Line
Section	17	0.4.0	. 0ED		
		10. Elevation (Show whether	Range 25E	NMPM Eddy Cour	ity
		4390	•		
11.	Check Ap	propriate Box to Indicate		PROFT or Other Data	
1	NOTICE OF INTÉ	NTION TO:		SEQUENT REPORT OF:	
	_		306	SEQUENT REPORT OF:	
PERFORM REME	DIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY A	BANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT	r 🗀
PULL OR ALTER	CASING		CASING TEST AND CE	MENT JOB X	
OTHER:			OTHER:		П
12. Describe Propo	sed or Completed Operations	(Clearly state all pertinent details, as	nd give pertinent dates includ	ing estimated date of starting any proposed	
work) SEE RU	TLE 1103.		and per vision and a page 2	one comment and of starting any proposed	
5-25-91 :	Donth 11 570!	(TD) Cot	.1		
J-2J-91.		(ID). Set cement p	olugs per instru	ctions from Mike Williams	
	C1 "H" + 1% F	i=20 & 5% calt	nu Atoka. Set	plug #1 at 11,072' w/ 50 sx	
	FL-20 & 5% sal	lt. Job complete at	- piug #2 at 10,	600' w/ 50 sx C1 "H" + 1%	
	12 20 a 5% bas	tt. Job complete at	- 3:43 p.m. woc	0% nours.	
5-26-91:	WOC 6½ hours	(Total WOC 13 hours)	. Tag plug at	10,510' (PBTD). Begin	
	running 5-1/2'	casing.	1 108 1148 41	10,510 (LBIB): Degin	
5-27-91:	Den +-+-1 - 6 0	7/0 /. F 1/0U			
J-27-91;	kan total of 2	248 jts 5-1/2" casin	ng as follows:		
			(See page	2)	
I hereby certify thatth	e information above is true and/h	complete to the best of my knowledge and b	<u> </u>		
		which it has near or my knownedge and p	ela.		

Sr. Production Clerk May 29, 1991 915/ TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 687-3551 ORIGINAL SIGNED BY (This space for State Use) MIKE WILLIAMS 4 1991 JUN SUPERVISOR, DISTRICT IT APPROVED BY-

CONDITIONS OF APPROVAL, IF ANY: