

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NOV - 7 1991

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Pardue Farms 27

8. Well No.

9

9. Pool name or Wildcat

East Loving Delaware

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Parker & Parsley Development Company ✓

3. Address of Operator

P.O. Box 3178, Midland, Texas 79702

4. Well Location

Unit Letter G : 2080 Feet From The East Line and 1880 Feet From The North Line

Section 27

Township 23S

Range 28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3044 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached daily report

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Randy R. Johnson

TITLE

Sr. Operations Engineer

DATE 11/6/91

TYPE OR PRINT NAME

Randy R. Johnson

915-683-4768
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 14 1991

WELL: PARDUE FARMS "27" #9 (DW)
PROJECT: PPDC - 93.90625%

STATE: NM
COUNTY: EDDY

TD: 6,800

Location: Staked by Dan R. Reddy 8/21/91. Unit Letter G, Sec. 27,
23 South, 28 East, 2080' FEL, 1880' FNL, Eddy County, NM.
Elev: 3044' G.L., Grace Rig #404.

Directions: F/Hwy 285 in Loving, New Mexico turn East on CR 714, which
is Ash Road, go 2.5+ miles to CG on South side of road
with Parker & Parsley sign. Turn right thru CG & drive
down main lease road to location.

10/21/91

FIRST REPORT: DEPTH 500'; WOC: MI, RURT, GRACE RIG #404.
SPUD 12-1/4" hole @ 2:00 p.m., 10/20/91. Drl to 500' in
5 hrs, gravel & redbed. Circ 1/2 hr & POOH. Ran 12 jts,
8-5/8", 24#, LP/STC csg & set @ 500'. Used TPS & 2 cent.
D-S cmt'd w/475 sx "C" + 2% CaCl. PD @ 9:45 p.m., 10/20/91.
Cmt circ w/200 sx. WOC & NU. MW 8.6#, Vis 32, pH NC.
ST - 3/4 deg @ 294', 1 deg @ 500'.

DSS 1

10/22/91

DEPTH 984'; DRLG: 484'/10-1/4 hrs, sd & anhy. MW 10#,
Vis 29, pH 10. Test csg & BOP to 500 psig, Ok. Ran 7-7/8"
bit & tag'd cmt @ 450'. Drl'd out cmt & drl'g ahead.
ST - 1-1/4 deg @ 662', 1-1/2 deg @ 810', 1-1/2 deg @ 963'.

DSS 2

10/23/91

DEPTH 1647'; DRLG: 663'/22-3/4 hrs, salt & anhy. MW 10#,
Vis 29, pH 10. ST - 1-3/4 deg @ 1118', 3 deg @ 1275',
2-3/4 deg @ 1370', 2-1/2 deg @ 1464', 2-3/4 deg @ 1589'.

DSS 3

10/24/91

DEPTH 2168'; DRLG: 521'/22-3/4 hrs, sh & anhy. MW 10#,
Vis 29, pH 10. ST - 2-1/2 deg @ 1684', 1-3/4 deg @ 1778',
2-1/4 deg @ 1938', 1-3/4 deg @ 2058', 2-1/4 deg @ 2153'.

DSS 4

10/25/91

DEPTH 2638'; DRLG: 470'/21-3/4 hrs, sh & anhy. MW 10#,
Vis 29, pH 10. ST - 2-3/4 deg @ 2340', 3 deg @ 2435',
2-1/4 deg @ 2528'.

DSS 5

PARKER & PARSLEY PETRO. CO.
DAILY OPERATIONS REPORT

(01/01/00 THRU 12/31/99)
WEST TEXAS SPRABERRY DISTRICT

PAGE 2

=====		
WELL: PARDUE FARMS "27" #9 (DW)	STATE: NM	TD: 6,800
PROJECT: PPDC - 93.90625%	COUNTY: EDDY	

10/26/91	DEPTH 3934'; DRLG: 1296'/22-1/4 hrs, salt & sd. MW 10#, Vis 29, pH 10. ST - 2 deg @ 2685', 1-3/4 deg @ 2905', 1 deg @ 3405', 1/2 deg @ 3903'. DSS 6	

10/27/91	DEPTH 4950'; DRLG: 1016'/23 hrs, sh & sd. MW 10#, Vis 29, pH 10. ST - 1 deg @ 4904'. DSS 7	

10/28/91	DEPTH 5696'; DRLG: 746'/23-1/2 hrs, sd & sh. MW 10#, Vis 31, pH 10, WL 11. ST - 1 deg @ 5404'. DSS 8	

10/29/91	DEPTH 6117'; DRLG: 421'/17 hrs, sd & sh. MW 10#, Vis 32, pH 10, WL 12. Trip for bit - 6 hrs. ST 1-3/4 deg @ 5781'. DSS 9	

10/30/91	DEPTH 6400'; DRLG: 283'/22-3/4 hrs, lm. MW 10.2#, Vis 32, pH 9.5, WL 8. ST - 1-1/4 deg @ 6273'. DSS 10	

10/31/91	DEPTH 6731'; DRLG: 331'/24 hrs, lm, sd & sh. MW 10.4#, Vis 32, pH 9.5, WL 10. Last circ @ 6576'; had 95% circ @ 6651'. DSS 11	

11/01/91	TD 6800'; PU DRILL PIPE: Made 69'/5 hrs, lm. RTD @ 10:30 a.m., 10/31/91. Circ 2 hrs, POOH/LDDP. Ran 14 jts, 4-1/2", 11.6#, K-55, LTC csg & hit bridge @ 572'. POOH LD csg, RD csg crew. PU DP & wash bridge dwn to 893'. MW 10.3#, Vis 31, pH 9, WL 20. ST - 1 deg @ 6800'. DSS 12	

11/02/91	TD 6800'; RU CSG CREW: MW 10.3#, Vis 45, pH 8, WL 6. 1-1/2 hrs PU DP, 8-1/4 hrs PU DP & wash bridges, 1/4 hr Wash to btm, 6 hrs Circ & mix mud, 3/4 hr Rig repair & 7-1/4 hrs LD DP.	

=====

WELL: PARDUE FARMS "27" #9 (DW)
PROJECT: PPDC - 93.90625%

STATE: NM
COUNTY: EDDY

TD: 6,800

11/03/91

TD 6800'; RDRT: Ran Weatherford FS, 4-1/2" 11.6#, K-55
LTC shoe joint, Weatherford FC, 4 jts 4-1/2" 11.6#, K-55
LTC csg, 1 short marker jt (25', T @ 6583') of same csg,
23 jts of same csg, Weatherford 4860-B DV Tool (T @ 5699')
& 149 jts of same csg. Set csg @ 6802' & D-S cmt'd 1st
stage w/80 sks 65/35 Poz-C + 4% gel + 3-1/2#/sk salt +
1/4#/sk celloflakes lead & 245 sks 10:10 Self Stress tail.
Circ 46 bbls cmt thru DV, plug dwn @ 2:40 p.m., 11/02/91.
2nd Stage, 680 sks 65/35 lead & 245 sks S.S. tail, plug
dwn @ 8:07 p.m., 11/02/91. Set slips, cut off RDRT. Rig
Released @ 11:00 p.m., 11/02/91.

11/04/91

(10/03/91 report cont'd) MORT.