Submit 3 Copies io Appropriate District Office	State of New Energy, Therals and Natural		Form C-163 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVAT		WELL AM NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic		5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		AUG 0 3 1992	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PRODIFFERENT RESER (FORM C-	CES AND REPORTS ON WIPOSALS TO DRILL OR TO DEEP WOR. USE "APPLICATION FOR 101) FOR SUCH PROPOSALS.)	en or peus backgo a	7. Lease Name or Unit Agreement Name
1. Type of Well: Off. GAS WELL X WELL	OTHER		Pardue Farms 27
2. Name of Operator Parker & Parsley Deve	lonment Co.		8. Well No.
3. Address of Operator			9. Pool same or Wildcat
P.O. Box 3178, Midlan	d, Texas 79702		East Loving (Delaware)
Unit Letter _G : _208	O Feet From The East	Line and 18	80 Peet From The North Line
Section 27	Township 23S		NMPM Eddy County
	10. Elevation (Show wheth	her DF, RKB, RT, GR, etc.) R	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INT			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING	·	CASING TEST AND CE	
OTHER:			test Bone Springs
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. See Attached Report			
I hereby certify that the information above is true SEGNATURE SEGNATURE	J. Holmed	and belief. Proration A	nalyst DATE 7/31/92 915- TELEPHONE NO. 683-4768
	J. Holmes		1 PACOL YM SWATSHALL
MIKE W	AL SIGNED BY ILLIAMS ISOR, DISTRICT II	TITLE	AUG 1 7 1992

CONDITIONS OF APPROVAL, IF ANY:

PARDUE FARMS 27 #9
"G", S. 27, T23S, R28E

SUNDRY NOTICE July 31, 1992

- 7/27/92 MIRU WSU. POH w/ rods, pmp & tbg. RIH w/ 3-7/8" Rk bit, bailer & 6 DC's on 2-3/8" tbg. Could not get any further than 3700' due to paraffin. POH w/ tools & SDFN.
- 7/28/92 RIH w/ 2-3/8" tbg to 4062'. Hot oil csg w/ 40 BO & 5 gal paraffin dispersant. POH w/ tbg. RIH, tag up on sd @ 6280'. CO to CIPB. Drl out CIPB & CO hole to 6713' (PBTD). SDFN.
- 7/29/92 RIH w/ tbg. Landed tbg @ 6202'. SN @ 6137', TAC @ 5757'. RIH w/ 2"x1-1/4"x16' pump. Space out & hung well on.
- 7/30/92 Pumping well. Recovering load wtr.