

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-01526870
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 23711
7. Lease Name or Unit Agreement Name WILLOW LAKE 22
8. Well No. 22-2
9. Pool name or Wildcat Und Malaga, East (Del)

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3006' GR
--

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
GRIFFIN PETROLEUM COMPANY

3. Address of Operator
550 West Texas Suite 1240 Midland, Texas 79701

4. Well Location
Unit Letter B : 990 Feet From The North Line and 1980 Feet From The East Line
Section 22 Township 24S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3006' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 11,650'. Spot 20 Sx cement on top. (3/22/99)
- 2) Circulate hole with mud laden brine.
- 3) Spot cement plugs from: 10,202'-10,069', 9482'-9349', 7700'-7567', 6275'-6142'.
- 4) Pulled cement bond log. TOC @ 4100'.
- 5) Set CIBP @ 4970'. Spot 500 gal acid across Delaware.
- 6) Perforated Delaware from 4778'-4810'. (3/26/99)
- 7) Swab tested.
- 8) Frac'd Delaware with 15,000 gals diesel and 46,000 #'s sand.
- 9) Put well on pump.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eric Griffin TITLE Vice President DATE 4/12/99
TYPE OR PRINT NAME Eric Griffin TELEPHONE NO. (915) 687-1042

(This space for State Use)

SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE 4-13-99

CONDITIONS OF APPROVAL, IF ANY: