RE	¢	E	۱	Y	E	D
76	Ç,	C	I	Y	C	υ

.jsF

Form 3160-5	UNITED STATES		JUN 1 9 19 92	FORM APPROVED
(June 1990)	DEPARTMENT OF THE IN BUREAU OF LAND MANAG		O. C. D.	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5 Lease Designation and Serial No.
Do not use this for	SUNDRY NOTICES AND REPOR m for proposals to drill or to deeper e "APPLICATION FOR PERMIT" 1	n or reentry	to a different reservoir.	NM 51073 6. If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICA	TE		7. If Unit or CA, Agreement Designation
 1. Type of Well Oil Well Well 2. Name of Operator Collins & Ware, 3. Address and Telephone No. 303 W. Wall, Sur 4. Location of Well (Footage, 14331 FSL & 1459 	8. Well Name and No. Muley Federal 9 API Well No. 10. Field and Pool, or Exploratory Area Horseshoe Bend (Strawn- 11. County or Parish, State Morrow) Eddy, New Mexico			
D CHECK AF	PROPRIATE BOX(s) TO INDICA	TE NATURI	E OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SU	BMISSION		TYPE OF ACTION	
Notice of In	tent [Abandonment Recompletion		Change of Plans
XX Subsequent	Report	Plugging Back Casing Repair		Won-Routine Fracturing
E. Final Aband	onment Notice	Altering Casing Other Inte	rmediate Casing	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

A 12.25" hole was drilled to 2050' K.B. on 6/3/92. Full returns were lost while drilling at 920' K.B. The hole was dry drilled to 2050'. A caliper log was run prior to running casing to determine the best possible setting depth for the external casing packer (a copy of Cardinal Wireline field print is enclosed). 9.625" 43.50, 47, and 53.50#/ft., N-80 and S-95 Buttress casing was run and set at 2050' K.B. Top of external casing packer at 828.41' from surface. Top of D.V. tool at 778.08' from surface. Cemented first stage: 475 sacks Hallaiburton Lite with 1/2#/sk., flocele, 2% CACL2, and 10# Cal-Seal. (2.01 cu.ft./sk. yield, 12.7#/gallon), tailed in with 200 sacks Premium Plus with 2% CALC2, (1.32 cu.ft./sk., 14.8#/gallon weight). Dropped bomb and waited 6 hours, cement did not circulate. Cemented Second Stage: with 275 sacks Halliburton Lite with 1/4# flocele/sk., 4% CACL2, and 6# Gilsonite, (1.84 cu.ft./sk., yield, 12.7#/gallon). Tailed in with 100 sacks Premium Plus with 4% CACL2 and 6# gilsonite (1.32 cu.ft./sk., 14.8#/gallon). Cement did not circulate Waited on cement for 3.5 hours and ran remperature survey, no cement top. Rig up to one-inch. Ran one inch 10 times with 35 sacks cement each run. Top of cement 686' after tenth run. Cemented with 255 sacks cement, circulated cement to surface. Set slips and nippled up, test to 2400 psig with rig pump. Cemented with a total of 570 sacks cement. Tested BOP, stack, safety valve to 5000 psig, tested hydrill 2000 psig.

NOTE: A cement Bond Log will be conducted on the 9.625" casing prior to running the next casing string.

Witnessed by the BLM					
14. I hereby certify that the foregoing is true and correct Signed Mission Torrect	Title Agent for Collins & Ware, Inc 6/8/92				
(This space for Federal or State office use)	A L				
Approved by Conditions of approval, if any:					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements