Su to Di

DEC 3 0 1992

Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-015-27016
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease  STATEXX FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		1232 <b>- 1992</b>	6. State Oil & Gas Lease No. V-3589
( DO NOT USE THIS FORM FOR PRODIFFERENT RESER	CES AND REPORTS ON WEL PPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEI 101) FOR SUCH PROPOSALS.)	OR PLANS MACKETS AF	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL XX WELL [	OTHER		Pauline ALB State
2. Name of Operator YATES PETROLEUM CORPOR	ATION		8. Well No.
3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., Art	esia, NM 88210	·	Wildcat Delaware
	O Feet From The South	Line and 660	Feet From TheEast Line
Section 32	Township 23S Ra	nge 31E	NMPM Eddy County
Section 32 Township 23S Range 31E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  3370' GR			
11. Check		Nature of Notice Re	enort or Other Data
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CE		MENT JOB
OTHER:		OTHER: Producti	on Casing, Perforate, Treat X
12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103.  TD 8160'. Reached TD 12-14-92. Ran 182 joints 5-1/2" 15.5# and 17# casing set 8160'. Float shoe set 8160', float collar set 8115'. DV tool set 6743'. Cemented in two stages. Stage 1 - 200 sx "H" w/8#/sx CSE, 5#/sx Gilsonite, .6% CF-14,.35% Thriftylite (yield 1.75, wt 13.6).  Tailed in w/65 sx "H", w/10% Thixad, 8#/sx Hiseal, 10% Salt (yield 1.38, wt 15.5), PD 6:26 AM 12-16-92. Bumped plug to 1100 psi. held OK. Circulated 45 sacks. Circulated thru DV tool 4 hrs. Stage 2 - 700 sx PSL "C" w/5#/sx Gilsonite, 5#/sx Salt, .4% CF-15 (yield 1.85, wt 12.7). Tailed in w/150 sx "H" w/8#/sx CSE, 5#/sx Gilsonite, .6% CF-14, .35% Thrifty-1ige (yield, 1.75, wt 13.6). PD 11:41 AM 12-16-92. Bump plug to 3000psi for 1 minute, OK. WOC 18 hours. Drilled DV tool at 6743'. Perforated 6467-7965' w/2742" holes (1 SPF) and treated as follows: Zone 1)7900, 04, 05, 09, 62, 64, 65 (7). Acidize w/1000g. 7½% NEFE. Frac'd w/3500g. 35# XL gel w/6000# 20/40 sand. Zone 2) 7719, 21, 22, 90, 93, 97 and 7802'(7). Acidize w/1000g. 7½% NEFE. Frac'd w/3000g. 35# and. Zone 3) 7492, 95, 96, 7538, 40, 42, 44 (7). Acidized w/1000g. 7½% NEFE. Frac'd w/3500g. 35# XL gel w/6000# 20/40 sand. Zone 4) 6467, 68, 70, 75, 77, 78 (6). Acidized w/1000g. 7½% NEFI Ihereby certify,that the information above is the and complete to the best of my knowledge and belief.  SIONATURE  TIME Production Supervisor  DATE 12-22-92  TIME OF PRINTNAME  Juanita Goodlett  TELEPHONE NO. 505/748-1471			
TYPEOR PRINT NAME Juanit	a Goodlett		<u>телерноне но. 505/748—1</u> 471

ORIGINAL SIGNED BY

SUPERVISOR, DISTRICT 19

MIKE WILLIAMS

(This space for State Use)

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-