

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

NOV 15 1993

WELL API NO.
30-015-27050

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-3479

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Pinnacle State

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

8. Well No.
1

2. Name of Operator
Fortson Oil Company

9. Pool name or Wildcat
Herradura Bend, East

3. Address of Operator
3325 W. Wadley Ste. 213, Midland, TX 79707

4. Well Location
Unit Letter L : 1980 Feet From The South Line and 300 Feet From The West Line
Section 36 Township 22South Range 28 East NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3125' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Install PU & Refrac ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/25/93 - MIRU COBRA PUL UT. Kill well 70 bbl prod wtr. Strip on BOP. Move 15 jts 2-7/8" tbg from #3 to #1. MI Open top tank to reverse SD into rig up circ line to tank.

10/26/03 - RU & kill well w/120 bbl prod wtr. Pick up 9 jts 2-7/8" tbg & tag sd @ 6188. Pump 140 bbl prod wtr-could not br circ. POOH w/tbg. Pick up 5-1/2 Model R pkr & locset RBP. RIH set & test RBP @ 6120. Pkr @ 6100' Test.

10/27/93 - Trip out of hole w/pkr. Lay dn pkr & pick up Ret head for RBP. RIH to 5920'. Flange up wellhead tree on top of BOP. Frac perfs @ 6013-62 @ 19,000 gal YF135 + 44,000# 16/30 sd @ avg rate 15 BPM. Sd conc 2 to 8 ppg avg. press 2600 psi.

10/28/93 - CK press. well on vacume. Pick up 5 jts 2-7/8 tbg & tag sd @ 6080'. 40' fill on RBP @ 6120. POOH w/tbg. Pick up Ret head & bulldog bailor. RIH & clean out to RBP. Rel RBP & start out of hole Plug hung @ 4420'. complete trip out of hole.w/RBP.

10/29/93 - Complete trip in hole w/bailor

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Judy Dixon TITLE Production Technician DATE 11/11/93
TYPE OR PRINT NAME Judy Dixon TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

NOV 12 1993

APPROVED BY _____ TITLE _____ DATE _____