1=6-7 1992

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

O. C. D. MANA CHANGE Form C-103 Revised 1-1-89

DISTRICT J P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL	CONSER'	VAT	NOL	DIVISIO	1(
	~ ~	**	0000		

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WEL	LL API NO.			
	30-015-27107			
5. I	Indicate Type of Lease STATEXX		FEE	
6. 5	State Oil & Gas Lease No.	•		
	V-3479			
///	7777777777777777777	///		////

	STATEKY FEE		
DISTRICTUII 1000 Rio Biazog Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.		
, , , , , , , , , , , , , , , , , , ,	V-3479		
SUNDRY NOTICES AND REPORTS ON WELLS			
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well:	-		
01.			
WELL XX WELL OTHER	Pinnacle State		
2. Name of Operator	8. Well No.		
Fortson Oil Company	9. Pool name or Wildcat		
3. Address of Operator			
301 Commerce Street, Suite 3301, Fort Worth, Texas 76102	Hast Herradura Bend, Helaware		
Unit Letter I: 1980 Feet From The South Line and 23	110 Feet From The Root Line		
Unit Letter : 9011 Peet From the 501111 Line and 2	THE PAST - LAST		
Section .36 Township 22 South Range 28 East	NMPM Edd v County		
7/////////////////////////////////////			
X/////////////////////////////////////			
11. Check Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data		
	SEQUENT REPORT OF:		
NOTICE OF INTENTION TO:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING CASING TEST AND CASING TE	EMENT JOB		
OTHER: OTHER: Perforat	ions Upper Delaware XX		
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and sive pertinent dates, inclu			

work) SEE RULE 1103.

Field operations began November 12, 1992 Set RBP at 6100' with 15' of fill on top (6085').

Spotted 250 gallons 10% Acetic Acid

Perforated 5984' - 6014' (62 holes) 2 SPF 0.42" holes.

Acidized with 1500 gallons 7.5% NEFE acid.

Fraced with 17,000 gallons Water Gel 40 plus 17,700# 16/30 mesh sand and 15,000# of Super LC in one stage.

0

perations complete N roducing from perfor	rations 5984' - 6014'.		
SIGNATURE MULL	tion above is the and complete to the best of my knowled	•	TELETIONE NO(915) 683–5511
(This space for State Use)	ORIGINAL SIGNED BY MIXE WILLIAMS		UEC 1 4 1992
	SUPERVISOR DISTRICT IT	7771 0	DATE