	1		
Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re		Form C-103 Revised 1-1-89
DI <u>STRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO P.O. Box 208		WELL API NO. 30-015-27451
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico		
DISTRICT III		ALC - 2 1000	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		AUG - 2 1993	6. State Oil & Gas Lease No. V-492
	CES AND REPORTS ON WEL		
	POSALS TO DRILL OR TO DEEPEN VOIR. USE "APPLICATION FOR PER 101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OAS WELL AND WELL X	/ OTHER	- ***	Malaga
2. Name of Operator			8. Well No.
Collins & Ware, Inc.			. 1
3. Address of Operator			9. Pool name or Wildcat Wildcat (Morrow)
303 W. Wall, Suite 220 4. Well Location			
Unit Letter <u>K</u> : 198	0 Feet From The South	Line and135	0 Feet From The West Line
Section 27	Township 24 South Ray		MFM Eddy County
	10. Elevation (Show whether I	DF, RKB, RT, GR, etc.) 2994.1' GR	
11. Check A	ppropriate Box to Indicate N	Nature of Notice, Re	port, or Other Data
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING	. "	CASING TEST AND CE	
OTHER: 70C-710	O" TAT. (Sy X	OTHER:	

`r√

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Cement did not tie back into 9.625" while cementing the 7.00" casing. A CBL log was ran and found top of cement at 5,200' KB. The 9.6352" casing was set at appx. 2,580' KB and cement circulated. The Bell Canyon Zone of the Delaware formation from 2,600' to 2,652' KB appears to be productive. We believe a braden head squeeze would force excessive cement into this productive interval with a strong possibility it could never be completed with a loss of possible oil and gas reserves.

- The oil and gas is contained between the cement top outside the 7.00" casing, the 9.625" casing and the 7.00" casing. The annular area is contained at the surface by a 5000 psig working pressure "B" section of the well head.

- For these reason, we are requesting approval to defer remedial cementing of this section until sometime in the future when a completion attempt is to be made.

- Log sections and a schematic well bore diagram depicting the various cement tops and casing seats are attached.

attaoned.		
I hereby certify that the information of the inform	tion above is the and complete to the best of my mowledge and belief.	DATE 7/29/93
TYPE OR FRONT NAME		TELEPHONE NO.
(This space for State Use)	ORIGINALISIGNED BY MIKE WILLIAMS	AUG 2 7 1993
AFTROVED BY		DATE
CONDITIONS OF AITFROVAL, IF	ANY:	