

5. Lease Designation and Serial No.

NM-14140

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Nash Unit

8. Well Name and No.

Nash Unit #19

9. API Well No.

30-015-27590

10. Field and Pool, or Exploratory Area

Nash Draw Brushy Canyon

11. County or Parish, State

Eddy County, NM

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Strata Production Company

3. Address and Telephone No.

P.O. Box 1030, Roswell, NM 88202-1030

505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2202' FSL & 2201' FEL  
Section 12-23S-29E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Put on pump

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

09/19/94: RU Cobra Well Service. Load tubing with 2% KCL. Release packer. PU tubing. Tag sand. TOH with packer. TIH with bailer. Clean out 157' of sand to 7220'. TIH with production string. Set TA at 6630'. Set SN at 7046' with 4' perf sub and MJ. ND BOP. Pull 18 points on TA. Flange up. Prep to run rods. SISD.

09/20/94: PU and TIH with PAP pump, subs, rods, and liner. Space out. Build wellhead. Long stroke pump to check pump action. RD. Prep to set pumping unit and make electrical tie-in. SISD.

09/23/94: Set 456 pumping unit with electric motor. Hang on. Tie-in electricity.

09/24/94: Start pumping unit.

14. I hereby certify that the foregoing is true and correct

Signed

Carol G. Garcia

Title Production Records Manager

Date 10/3/94

(This space for Federal or State office use)

Title

Date

Approved by

Conditions of approval, if any

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side