Submit 3 Copies to Appropriate District Office

١

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

rawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

**WELL API NO.** 30-015-27614

5. Indicate Type of Lease

DISTRICT III	STATE LA FEE L.		
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. V - 4137		
SUNDRY NOTICES AND REPORTS ON WELLS			
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name		
1. Type of Well:			
WELL COTHER	Milano State		
2. Name of Operator	8. Well No.		
Energex Co.  3. Address of Operator	#1		
100 North Penn. Roswell, NM 88201	9. Pool name or Wildcat Wellew Lake		
4. Well Location	With Delaware Pelauare		
Unit Letter H: 2110 Feet From The north Line and 890	Feet From The east Line		
Section 36 Township 24s Range 28e	NMPM Eddy County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM County		
//////////////////////////////////////			
11. Check Appropriate Box to Indicate Nature of Notice, F	Report, or Other Data		
	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING CASING TEST AND C	CASING TEST AND CEMENT JOB		
OTHER: OTHER: Perf	OTHER: Perf additional zone		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.	iding estimated date of starting any proposed		
1.) Set RBP @ 4850'. Test to 1500#.			
💁.) Perf Brushy Canyon 4798-4808' 2 spf 22 holes.			
3 ) Acidize with 750 gallope 7 1/2% and 77 hallo			

PEHFORM REMEDIAL WORK PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		отнея: Perf additional	zone X
12. Describe Proposed or Completed Operations (Clearly state all pertinent dwork) SEE RULE 1103.	etails, an	d give pertinent dates, including estimated date of	starting any proposed
1.) Set RBP @ 4850'. Test to 1500#.			
<b>@.</b> ) Perf Brushy Canyon 4798-4808' 2	spf	22 holes.	
3.) Acidize with 750 gallons 7-1/2%	and	33 balls.	
4.) swab test and.ret			4
5.) Pull PKR and RBP. and return to	pro	duction.	
I hereby certify that the information above is true and complete to the best of my knowle			
William K. Harret		Agent	11/20/07
SIGNATURE	m	<u>r</u>	DATE11/29/93
TYPEORPRINTNAME William R. Hansen			TELEPHONE NO. 622-4772
(This space for State Use)  ORIGINAL: SIGNED BY  MIKE WILLIAMS  APPROVED BY  SUPERVISOR, DISTRICT IF	тп	F	MOV 3 0 1993
CONDITIONS OF APPROVAL, IF ANY:			— DATE ————————————————————————————————————