Form 3160-5 (June 1990)

N.M. Oil Confivision

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 151. 1st Street BUREAU OF LAND MANAGEMENT 151. NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Lease	Designation	and Serial No.	
	NIA O	LEGE	

		NM-81586			
o not us	SUNDRY NOTICES A se this form for proposals to dril Use "APPLICATION FO	6. If Indian, Allottee or Tribe Name			
	SUBMIT	7. If Unit or CA, Agreement Designation			
. Type of W					
Oil Well . Name of C		8. Well Name and No. Riverbend Federal #5			
Pogo Pro	oducing Company		9. API Well No.		
	and Telephone No.	45005 0400	30-015-27977		
	x 10340, Midland, TX 79702-7340 (9	10. Field and Pool, or Exploratory Area			
	of Well (Footage, Sec., T., R., M., or Survey Desc	Cedar Canyon Delaware			
2310' FN	NL & 660' FEL, Section 22, T24S, R29I <i>860</i>	11. County or Parish, State Eddy County, NM			
2.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION TYPE OF ACTION				
	Notice of Intent	Abandonment	Change of Plans		
		Recompletion	New Construction		
	Subsequent Report	Plugging Back	Non-Routine Fracturing		
		Casing Repair	Water Shut-Off		
	Final Abandonment Notice	Altering Casing	Conversion to Injection		
		Other Add pay to Delaware	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
3. Describe	Proposed or Completed Operations (Clearly sta ally drilled, give subsurface locations and measu	te all pertinet details, and give pertinent dates, including estimated date red and true vertical depths for all markders and zones pertinent to this	of starting any proposed work. If well is		
arrections					
		2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004'	•		
03/30/00		2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004'	•		
03/30/00 03/31/00	TIH w/ RBP & set @ 5100'. Test to Acdz perfs 4903'-5067' (OA) w/ 1500	2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004'	•		
03/30/00 03/31/00	TIH w/ RBP & set @ 5100'. Test to Acdz perfs 4903'-5067' (OA) w/ 1500 Release RBP @ 5100' & POOH. TI	2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004' Digals 7-1/2% HCL. Swab. H w/ production equipment. Return well to production. ACCEPTED FOR I	(2 SPF) & 4903'-4930' (1 SPF).		
03/30/00 03/31/00 04/04/00 4. I hereby	TIH w/ RBP & set @ 5100'. Test to Acdz perfs 4903'-5067' (OA) w/ 1500' Release RBP @ 5100' & POOH. TI	2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004' Digals 7-1/2% HCL. Swab. H w/ production equipment. Return well to production. ACCEPTED FOR I	(2 SPF) & 4903'-4930' (1 SPF).		
03/30/00 03/31/00 04/04/00 4. I hereby	TIH w/ RBP & set @ 5100'. Test to Acdz perfs 4903'-5067' (OA) w/ 1500 Release RBP @ 5100' & POOH. TI OCRECA ARY Certify that the foregoing is true and correct for Federal or State office use)	2000# ok. Perf Delaware 5056'-67' (2 SPF), 4984'-5004' Digals 7-1/2% HCL. Swab. H w/ production equipment. Return well to production. ACCEPTED FOR I	(2 SPF) & 4903'-4930' (1 SPF).		

GECEINED