		811 S. 1s	Cons vivision
21/0 6	UNITED STA	• • • • • • •	IN 88210-2834 FORM APPROVED
rm 3160-5 ne 1990)	DEPARTMENT OF TH		Budget Bureau No. 1004-0135 Expires: March 31, 1993
1	BUREAU OF LAND MA		5. Lease Designation and Serial No.
		ULI .	NM-84866
Do not use this form	INDRY NOTICES AND RE	epen or reentry to a differe	6. If Indian, Allottee or Tribe Name
	SUBMIT IN TRIP	LICATE	7. If Unit or CA, Agreement Designation
Type of Well			8. Well Name and No.
Model Gas Well Gas Well Name of Operator	Other	·	COCHITI "8" FEDERAL #2
MARALO, INC.			9. API Well No.
Address and Telephone No.			30-015-28618
P. 0. BOX 832, MI	DLAND, TX 79702	(915)	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)			MALĄGA; DELAWARE
660. FNL & 1980. F	WL, SECTION 8, T24S, R29E,	UNIIC	11. County or Parish, State
			EDDY, NM
CHECK AP	PROPHIATE BOX(S) TO INI	JUATE NATURE OF NO	FICE, REPORT, OR OTHER DATA
TYPE OF SUE	BMISSION	TYP	E OF ACTION
X Notice of Inte	tnt		Change of Plans
			New Construction
Subsequent R	eport	Plugging Back	Non-Routine Fracturing
—		Casing Repair	Water Shut-Off
	nment Notice	Altering Casing	Conversion to Injection
Final Abando			
Final Abando		Other	Dispose Water (Note: Report results of multiple completion on Well
		Other	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Complet give subsurface locations	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille
Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a 	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille
Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille
Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Til-	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a 	Other ils, and give pertinent dates, including estin ill markers and zones pertinent to this wo PF @ 6350-6362' (total 25 holes).	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)*
Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. TII- SWSCO GR/CN	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. I w/ 4" camer guns and shoot 2 JSF	Other ils, and give pertinent dates, including estin ill markers and zones pertinent to this wo PF @ 6350-6362' (total 25 holes).	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)*
Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL RUPU. TOH w RU wireline. Tilly SWSCO GR/Ct TIH w/ tbg & pk Open pkr bypass	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. H w/ 4" camer guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he	Other ils, and give pertinent dates, including estin all markers and zones pertinent to this wo PF @ 6350-6362' (total 25 holes). De GR/CBL/CCL log is on depth	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log.
Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL I. RUPU. TOH w 2. RU wireline. Til- SWSCO GR/Ct 3. TIH w/ tbg & pk 4. Open pkr bypass	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM.	Other ils, and give pertinent dates, including estin all markers and zones pertinent to this wo PF @ 6350-6362' (total 25 holes). De GR/CBL/CCL log is on depth	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log.
Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Till SWSCO GR/Ch 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a ra 5. Swab back load 6. RU Dowell to fra	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand
 Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Tile SWSCO GR/Ct 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a rate down tbg at a rate down tbg at a rate for the subsurface of the	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY_CANYON_PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased ho r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand
 Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Tile SWSCO GR/Ct 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a rate down tbg at a rate down tbg at a rate for the subsurface of the	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY_CANYON_PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. i. ic perfs 6350 - 6362' w/ 30,500 gals resin-coated sand down tbg at +/- 10 atlow_gel to break.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand
 Describe Proposed or Complet give subsurface locations PROPOSED ADDITIONAL RUPU. TOH w RU wireline. Til- SWSCO GR/Ct TIH w/ tbg & pk Open pkr bypass down tbg at a rate Swab back load RU Dowell to fra + 64,500# 16/30 psi. Shut well in to a Swab and evalu 	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY_CANYON_PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. i. ic perfs 6350 - 6362' w/ 30,500 gals resin-coated sand down tbg at +/- 10 atlow_gel to break.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand g pressure of 3600
Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Till SWSCO GR/CH 3. TIH w/ tbg & pk 4. Open pkr bypass: down tbg at a rate of the second secon	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. H w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. I. I. I. I. I. I. I. I. I. I. I. I.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand g pressure of 3600
 Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. THE SWSCO GR/CH 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a rate for subsurface down tbg at a rate f	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. 1 w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. 1. to perfs 6350 - 6362' w/ 30,500 gals resin-coated sand down tbg at +/- 11 tillow gel to break. tate. kr. TIH w/ retrieving head and pull f	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand g pressure of 3600
 Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL RUPU. TOH w. RU wireline. Tile SWSCO GR/CH TIH w/ tbg & pk Open pkr bypasse down tbg at a rest of the second secon	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. I w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. I. I. I. I. I. I. I. I. I. I. I. I.	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. mud clean-out acid 16/30 ottawa sand g pressure of 3600 RBP. OCTOBER 7, 1005
 Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w 2. RU wireline. Till SWSCO GR/CH 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a rate down t	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. I w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. i. i. i. c perfs 6350 - 6362' w/ 30,500 gals resin-coated sand down tbg at +/- 10 illow gel to break. iate. kr. TIH w/ retrieving head and pull f poing is true and correct	Other	Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. 16/30 ottawa sand g pressure of 3600 RBP. Date OCTOBER 7, 1996
Describe Proposed or Complete give subsurface locations PROPOSED ADDITIONAL 1. RUPU. TOH w. 2. RU wireline. Till SWSCO GR/CH 3. TIH w/ tbg & pk 4. Open pkr bypass down tbg at a rate 5. Swab back load 6. RU Dowell to frate + 64,500# 16/30 psi. 7. Swab and evalut 8. TOH w/ tbg & pt 1 hereby certify, that the foreg Signed State of Federal or State	ted Operations (Clearly state all pertinent deta and measured and true vertical depths for a <u>BRUSHY CANYON PAY</u> /tbg, rods, & pump. I w/ 4" carrier guns and shoot 2 JSF NL/LDT log run 09/10/95. Cased he r to 6300'. Set pkr. s. Spot acid to pkr. Close bypass. A ate of +/- 3 BPM. I. i. ic perfs 6350 - 6362' w/ 30,500 gals resin-coated sand down tbg at +/- 10 illow gel to break. iate. kr. TIH w/ retrieving head and pull f coing is true and correct ALEXIS C. SWOBODA	Other	Completion or Recompletion Report and Log form.) mated date of starting any proposed work. If well is directionally drille rk.)* Depths picked on with OH log. 16/30 ottawa sand g pressure of 3600 RBP. Date OCTOBER 7, 1996

*See Instruction on Reverse Side