

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Maralo, L.L.C.

3. Address and Telephone No.

P.O. Box 832, Midland, TX 79702 (915) 684-7441

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980' FWL, Section 8, T24S, R29#, Unit C

5. Lease Designation and Serial No.

NM 84866

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Cochiti "8" Federal #2

9. API Well No.

30-015-28618

10. Field and Pool, or Exploratory Area

Malaga - Delaware

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 6-26-00 (1) Set CIBP @ 5600', two runs w/ bailer, dumped cmt. on CIBP, WOC & tagged w/ WL @ 5570'.
6-27-00 (2) Circ. hole w/ mud.
6-27-00 (3) Cut 5-1/2" csg. @ 2770', POOH w/ 5-1/2".
6-28-00 (4) Spot 65 sx 2820-2670' w/ 2% Calcium Chloride, cover 8-5/8" shoe and 5-1/2" stub. WOC & tagged cmt. @ 2639'.
6-29-00 (5) Spot 35 sx cmt. 705-600', w / 2% calcium chloride, WOC & tagged cmt. @ 557'.
6-29-00 (6) Spot 10 sx 30' - Surface.
(7) Cut wellhead off, cover pit, clean location, install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title Agent

Date 06/30/00

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: