Form 3160-5 (June 1990)	DEPARTMEN	TED STATES 1301 W. G	Cons. IV-Dist. 2 rand Avenue NM 8991 Pilleau No. 1004-0135 NM 8991 Pilleau No. 1004-0135 March 31, 1993
Do not us	SUNDRY NOTICES se this form for proposals to dri	LAND MANAGEMENT AND REPORTS ON WELLS Il or to deepen or reentry to a different reservoi DR PERMIT-'' for such proposals	5. Lease Designation and Serial No. NM-0417696 6. If Indian, Allottee or Tribe Name r.
	SUBMIT	7. If Unit or CA, Agreement Designation	
3. Address ar P. O. Box 4. Location of	Gas Well Other	I I I I I I I I I I I I I I I I I I I	8. Well Name and No. Lost Tank 4 Federal #1 9. API Well No. 30-015-28727 10. Field and Pool, or Exploratory Area Lost Tank Delaware West 11. County or Parish, State
12.		TO INDICATE NATURE OF NOTICE, REPORT,	
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
	Subsequent Report Final Abandonment Notice	Plugging Back Casing Repair Altering Casing Other Add Delaware Perfs	Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recordingtion Report and Log form.)
13. Describe directiona	Proposed or Completed Operations (Clearly st Ily drilled, give subsurface locations and meas	ate all pertinet details, and give pertinent dates, including estimated dat ured and true vertical depths for all markders and zones pertinent to this	e of starting any proposed work. If well is
01/28/02	POOH w/ rods & pump.		
01/29/02	02 Set CIBP @ 7700'. Perf Delaware 7254'-69' w/ 2 spf. Test CIBP to 3000# ok. Acdz 7254'-69' w/ 1000 gals 7-1/2% HCL.		
02/01/02	02/01/02 Frac 7254'-69' w/ 27,000# 20/40 Ottawa sand.		
02/07/02	RIH w/ production equipment. Retu	Im well to production.	
			FEB 1 5 2002

02/07/02	
and willfully to make to any department or agency of the United States any false, fictitious or fraudulent	
false	

See Instruction on Reverse Side



5005 FEB 11 AM 10: 29

BUREAU OF LAND MGMT. ROSWELL OFFICE