

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-015-29007

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

OXY USA Inc.

16696

3. Address of Operator

P.O. Box 50250 Midland, TX 79710-0250

7. Lease Name or Unit Agreement Name

Hugerman

19046

8. Well No.

1

9. Pool name or Wildcat

Undesignated Carlshad Delaware S.

4. Well Location

Unit Letter K : 1650 Feet From The South Line and 2200 Feet From The West Line

Section

30

Township

22S

Range

27E

NMPM

Eddy

County

10. Elevation (Shore - neither DF, RKB, RT, GR, etc.)

3184

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: _____

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See other side

Notify N.M.D.C.C. in sufficient time to witness

TAG

DEC 17 '96

O. C. D.

ACTING SECRETARY

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David Stewart

TITLE

Regulatory Analyst

DATE

12/16/96

TYPE OR PRINT NAME

David Stewart

TELEPHONE NO. 9156855717

(This space for State Use)

Jim Al Kim

TITLE

DATE

12-30-96

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

**P&A Procedures
Hagerman #1**

- 1) Displace hole with 10 ppg mud. Set CIBP at 4900' and spot 100' of cement on top
- 2) FU to 3600'. Spot a 200' cmt plug across DV tool at 3516'.
- 3) FU to 2700'. Spot a 200' cmt plug from ^{1600' 1800'} ~~2700' to 2500'~~
- 4) FU to 510'. Spot a 200' cmt plug across 13-3/8" shoe at 410' from 510' to 310'.
FOOH. WOC 4 hrs and tag top of plug at 310'. POOH
- 5) ND BOP's. Spot 10 sx surface plug. ND WH. Cut off 8-5/8" casing. Weld on plate
and dry hole marker. RD PU.
- 6) Rip and reseed road and location. Repair damage to city streets.