Submit 3 copies		New Mexico	CV Form C-103 +
to Appropriate District Office	Energy, Minerals and Natural Resources Department		nt Revised 1-1-89
DISTRICT I	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2	088	30-015-29170
DISTRICT II	Santa Fe, New Mexic	co 87504 -2088	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210			STATE FEE S
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
SUNDRY NOTICES AND REPORTS ON WELLS			
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			
1. Type of Well:	(FORM C-101) FOR SUCH PROPOSALS.)		WEST LOVING FEE
OIL GAS Well Well	OTHER	4	
2. Name of Operator MYCO INDUSTRIE:	S INC		8. Well No.
		RECEIVED	9. Pool name or Wildcat
CASS DRAW-DELAWARE			CASS DRAW-DELAWARE
4. Well Location Unit Letter F : 1980	Feet From The NORTH	Line and 1980	Feet From The WEST Line
Section 23	Township 23S	Range 29E NMP	M EDDY County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF IT	NTENTION TO:		UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON KX	REMEDIAL WORK	ALTERING CASING
		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING (	DPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	ENT JOB [
OTHER:		OTHER:	
		· · · · · · · · · · · · · · · · · · ·	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
WELL IS UNECONOMICAL TO PRODUCE AT CURRENT RATE OF 135-BW PER MONTH AND 3-BO PER MONTH W/GAS TSTM. NO ADDITIONAL ZONES OF INTEREST ARE IDENTIFIED. 8-5/8" IS SET @ 376' (CMT. CIRC.) AND 5-1/2" IS SET @ 3477' (CMT.CIRC.). PROPOSE P/A AS FOLLOWS WITHIN NEXT 90-DAYS:  (A) 24-HR NOTICE OCD (B) CIRC. W/10# MUD (C) SET A CIBP @ 3200' ABOVE PERFS (3256-96')  (14-HOLES ACID ONLY) W/50-SX. (D) 50-SX PLUG INSIDE 5-1/2" ABOVE/BELOW 8-5/8" SHOE @ 376' (E) 10-SX PLUG @ SURFACE (F) SET MARKER, CLEAN LOCATION & NOTIFY OCD FOR FINAL INSPECTION.			
*TAG			
N - 2 - 2			
•			
Thereby certify that the information above is true and complete to the best of my knowledge and belief.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE AINIMUM, PELS INLE OPERATIONS MGR. DATE 2/20/98			
Type or print name			TELEPHONE NO. (505) 748-4274
(This space for State Use)			
APPROVED BY Marc Sublifield	THE FIELD	Pep: II DATE	3-9-96

CONDITIONS OF APPROVAL, IF ANY: