

37. SUMMARY OF POROUS ZONES (show all important zones of porosity and cor- thereof; cored intervals; and all
 drill-stem tests, including depth interval tested, cushion used, time tool open, flow and shut-in pressures, and
 recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Lamar	3125'		
Delaware	3153'		
Bone Spring	6823'		

38. GEOLOGICAL MARKERS			38. GEOLOGICAL MARKERS		
NAME	TOP		NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH		MEAS. DEPTH	TRUE VERT. DEPTH