					1	clsf
Form 3160-5	UN	TED STATES				FORM APPROVED
(June 1990)	DEPARTME	NT OF THE IN	TERIOR			Budget Bureau No. 1004-0135
		LAND MANA				5. Lease Designation and Serial No.
						NM-40655
	SUNDRY NOTICES	AND REPOR	TS ON WEL	LS		6. If Indian, Allottee or Tribe Name
Do not use this	s form for proposals to d				eservoir.	
	Use "APPLICATION FO	R PERMIT-"	for such prope	osais		
SUBMIT IN TRIPLICATE						7. If Unit or CA, Agreement Designation
I. Type of Weil					_	
	feil Other		n - marte in a state	1081-	12	8. Well Name and No.
2. Name of Operator			A Deall 28	A DE MARCH	45	Amax 24 Federal #13
-	icing Company	4		Š <sup>V</sup>	<u> </u>	9. API Well No.
3. Address and Telepho			20	N	نې د .	30-015-29332
	10340, Midland, TX		0 (915) <b>6</b> 8	2-68272 ~~ /		10. Field and Pool, or Exploratory Area
4. Location of Well (Fo	botage, Sec., T., R., M., or Survey D	escription)	14	- OCD SCA	2	Ingle Wells Delaware
1310' ESI	& 330' FWL, Sectio	n 2/1 T235	P31F	$\sim \pi_{IL}$	Sta N	11. County or Parish, State
1010 102	a JJU TML, JECTIO	11 24, 1200,		in the second second	্র ১	Eddy County, NM
. <u></u>				<u>`</u> {202		
12. CHEC	K APPROPRIATE BOX	s) TO INDICA	TE NATURE	OFNETHO	PEPOR	T, OR OTHER DATA
TYPE (	OF SUBMISSION			TYPE O	ACTION	
Notis	ce of Intent		Abandonment			Change of Plans
	APPENDAT	no pennan	Recompletion			New Construction
Subs	equent Report		Plugging Back			Non-Routine Fracturing
		0 (007	Casing Repair			Water Shut-Off
Final	Abandonment Notice	3 1997	Altering Casing			Conversion to Injection
		000		, Set Surf	<u>ace, In</u> t	
		······································	& Pro	od Csg ·		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Chearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud & Set Surface Csg - MIRt TMBR/Sharp #10. Spud well @ 0245 hrs CST 12/21/96. Drilled 17-1/2" hole to 850'. TD reached @ C315 hrs CST 12/22/96. Ran 19 jts 13-3/8" 54.5# J-55 ST&C csg. Cmt'd w/ 700 sxs "C" Lite w/ 2% CaCl<sub>2</sub> 12.4 ppg. Tailed w/ 200 sxs "C" w/ 2% CaCl<sub>2</sub> 14.8 ppg. Plug down @ 1145 hrs CST 12/22/96. Recovered 110 sxs excess cmt. Total WOC 24 hrs. Test BOP's to 1000#. Intermediate Csg - Drilled 11" hole 850' to 4310'. TD reached @ 0600 hrs CST 12/27/96. Ran 96 jts 8-5/8" 24# & 32# J-55 ST&C csg. Float shoe @ 4310'. Float collar @ 4263'. Howco cmt'd w/ 1120 sxs Halliburton Lite @ 12.7 ppg fcllowed by 200 sxs Premium Plus @ 14.8 ppg. Plug down @ 1800 hrs CST 12/27/96. Recovered 105 sxs excess cmt. ND BOP's & make cut-off. Weld on wellhead & test to 1500 psi. NU BOP's & test to 150C psi. TD & Production Csg - Drilled 7-7/8" hole to 6700'. TD reached @ 0830 hrs CST 12/31/96. Logged well w/ Western Atlas. Ran 149 jts 5-1/2" 15.5# J-55 LT&C csg. Float shoe @ 6700'. Float collar @ 6652'. Stage tool @ 4262'. Howco cmt'd list stage w/ 625 sys Cl "C" + 12 ppg Gilsopite + 2 % ppg.

6652'. Stage tool @ 4262'. Howco cmt'd 1st stage w/ 625 sxs Cl "C" + 12 pps Gilsonite + 2.8 pps KCL + .6% H322 @ 14.1 ppg. Lisplace cmt & land plug. Drop bomb & open DV tool. Circulated 5 hrs between stages. Recovered 36 sxs excess cmt. Cmt 2nd stage w/ 460 sxs Halliburton Lite @ 12.4 ppg. Plug down @ 2200 hrs CST 01/C1/97. Circ 106 sxs excess cmt. ND BOP's & make cut-off. Weld on wellhead & test to 2500 psi.

I hereby centry pair the foregoing of the and correct Signed	Tide Senior Operations Engineer	Date <u>4/1/97</u>
(This space for Federal or State office use)		
Approved by Conditions of approval, if any:	Title	Date
	wingly and willfully to make to any department or agency of the United Sta	