Submit 3 Copies to Appropriate District Office		f New Mexico Natural Resources Departms	Form C-103 Revised 1-1-89
<u>DISTRICT J</u> P.O. Box 1980, Hobbs, NM 88240 <u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210 <u>DISTRICT III</u> 1000 no Brazos Rd, Aztee, NM 87410	P.O	VATION DIVISION D. Box 2088 Mexico 87504-2088	WELL API NO. 30-015-29407 5. Indicate Type of Lease STATE STATE 6. State Oil & Gas Lease No. K-952
(DO NOT USE THIS DIF	JNDRY NOTICES AND REPORTS OF FORM FOR PROPOSALS TO DRILL OR TO DE FERENT RESERVOIR. USE "APPLICATION FO (FORM C-101) FOR SUCH PROPOSALS	EEPEN OR PLUG BACK TO A OR PERMIT	7. Lease Name or Unit Agreement Name TODD "36P" STATE
	CORPORATION (NEVADA)	BECEIVED	8. Well No. 19 9. Pool name or Wildcat
3. Address of Operator 20 NORTH BROAD	WAY, SUITE 1500, OKLAHOMA CITY, OKLAH	OCD ARTESIA IOMA 73(02, (405) 235-3611	Ingle Wells (Delaware)
4 Well Location Unit Letter <u>P: 773</u>	B Feet From The	Line and 571 Feet	From The <u>EAST</u> Line
Section 36		31E NMPM ther DF, RKB, RT, GR, etc.)	Eddy County
NOTIC	Check Appropriate Box To Indicate N E OF INTENTION TO:		her Data ENT REPORT OF:
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING	K PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB	ALTERING CASING Image: Casin
OTHER:		OTHER: <u>Completion</u>	X

=

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

08-05-97 thru 08-27-97

Ran bit, csg scraper and DC's on 2 7/8" tbg. Tagged up at 5508'. Press tested csg to 2500 ps					
Drld cement and DV tools. Press tested csg and DV tool to 2500 psi, held OK. Continued in I	hole, tagged				
8587' PBTD. Circ'd hole clean. RU Wedge WL. Ran CBL 8588-3030'. TOC 3254'.					
Perf'd LBC as follows: "A" at 8328', 8326', 8324', 8322', 8320' and 8318' w/1 JSP2' for 6 holes; "A" at					
8312', 8308' and 8301' w/2 JSP1' for 6 holes; "B" at 8262', 8260', 8258', 8256', 8254', 8252',					
8248' w/1 JSP2' for 8 holes; "B" at 8246' w/1 hole; "C" at 8230', 8229' and 8228' w/1 JSP1' for 3 holes;					
total 24 holes (.40" EHD). Set packer at 8166'.					
Acidized perfs 8228-8328' down tbg w/1500 gals 7 1/2% NeFe acid + 50 BS at AIR 7.2 BPM w/2356 psi.					
ISIP on vacuum. TOH w/packer.					
Frac'd perfs 8228-8328' down csg w/33,500 gals 30# X-Link gel + 121,000# 16/30 Ottawa sd	+ 40,000#				
16/30 RC sd at AIR 40.3 BPM w/702 psi. ISIP 2800 psi. (Continued on	reverse.)				

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Candace R. Graham_	TITLE ENGINEERING TECHNICIAN	DATEOctober 2, 1997
TYPE OR PRINT NAME Candace R. Graham		TELEPHONE NO. (405) 235-3611
(This space for State use) OPACIAL STATES OF THE W. GUR Approved by OPACIAL STATES OF THE W. GUR Conditions of approval, if any:	. TITLE	NOV 5 1997

API 30-015-29407 Devon Energy Corporation (Nevada) Todd "36P" State #19 773' FSL & 571' FEL, Section P-36-23S-31E, Eddy Cnty, NM Sundry Notice of Completion 10/2/97 Page Two

<u>08-05-97 thru 08-27-97</u> (Continued from the front.)

RU Foam unit. Cleaned out sand 6838-8588'. Circ'd hole clean. Set RBP at 8212'. RU Wedge WL. Perf'd LBC w/1 JSPF as follows: "E" at 8174-8194' w/21 holes; "D" at 8136-8140' w/5 holes; total 26 holes (.40" EHD). Set packer at 8010'.

Acidized perfs 8136-8194' down tbg w/1500 gals 7 1/2% NeFe acid + 55 BS at AIR 7.3 BPM w/2619 psi. ISIP on vacuum. TOH w/packer.

Frac'd perfs 8136-8194' down csg w/32,250 gals 30# X-Link gel + 115,500# 16/30 Ottawa sd + 42,500# 16/30 RC sd at AIR 40.1 BPM w/1006 psi. ISIP 4200 psi.

RU foam unit. Cleaned out sand to 8212'. Circ'd hole clean. TOH w/RBP.

RU Computalog. Perf'd w/1 JSPF as follows: LCC "G" at 6714'-6720' w/7 holes; LCC "C" at 6976-6980' w/5 holes; UBC "A" at 7358-7372' w/15 holes; MBC "H" at 7418-7428' w/11 holes; MBC "F" at 7568-7570' w/3 holes; MBC "D" at 7677-7679' w/3 holes; MBC "C" at 7736-7738' w/3 holes; total 47 holes (.40" EHD). Set RBP w/ball catcher at 7800', packer at 7505'.

Acidized perfs 7568-7738' down tbg w/1000 gals 7 1/2% NeFe acid + 18 BS at AIR 5.8 BPM w/3400 psi. ISIP on vacuum.

Reset RBP at 7505', packer at 7287'.

<u>-</u>

Acidized perfs 7358-7428' down tbg w/1000 gals 7 1/2% NeFe acid + 50 BS at AIR 5.5 BPM w/2400 psi. ISIP on vacuum.

Reset RBP at 7050', packer at 6910'.

Acidized perfs 6976-6980' down tbg w/750 gals 7 1/2% NeFe acid + 10 BS at AIR 5.8 BPM w/3600 psi. ISIP on vacuum.

Reset RBP at 6800', packer at 6658'.

Acidized perfs 6714-6720' down tbg w/750 gals 7 1/2% NeFe acid + 14 BS at AIR 5.9 BPM w/2955 psi. ISIP 292 psi.

TOH w/RBP and packer. TIH w/RBP w/out ball catcher, set at 7800'. Set packer at 6658'. Swabbed back load water. TOH w/packer and RBP. Bailed sand to 8587'.

Ran 2 7/8" tbg, SN set at 8343'. Ran pump and rods. Set pumping unit, HU elec. Began pump testing.