

ATTACHMENT TO C101

CONCHO RESOURCES INC. BERETTA '15' STATE NO. 1 – PLUGBACK JULY 21, 1999

1. MIRU. Kill well w/ 2% KCL water. ND tree & NU BOP. POOH w/ tbg.
2. RU WL. RIH w/ CIBP & set @ 11480'. Dump 35' of cmt on top (Abandoning Morrow pool.)
3. RIH w/ WL guide, 10' sub, F nipple, 1 jt 2-3/8", 1X pkr, on/off tool & 2-3/8" tbg to 10,425'. Circ 2% KCL w/ oxygen scavenger to fill hole.
4. Set pkr. ND BOP & NU tree.
5. Swab well down to 9000'.
6. RU WL. RIH w/ 11/16" perf gun & perf Atoka @ 10525-30' w/ 4 SPF (21 shots total).
7. Swab well to kick off. RDMO PU. Evaluate for additional stimulation.