

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30015-29449

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name  
Beretta '15' State

Well No.  
1

Pool name or Wildcat  
CARLSBAD MORROW SOUTH

Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

Name of Operator  
CONCHO RESOURCES INC.

Address of Operator  
110 W. LOUISIANA STE 410; MIDLAND TX 79701

Well Location

Unit Letter N : 660 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 15 Township 23S Range 26E NMPM EDDY County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3317 GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

OTHER: Add Additional Morrow Pay ☒

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
ALTERING CASING ☐  
PLUG AND ANBANDONMENT ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO ADD ADDITIONAL MORROW PAY IN THE BERETTA '15' STATE NO. 1 WELL ACCORDING TO THE FOLLOWING PROCEDURE.

1. MIRU. Kill well w/ 2% KCL water. ND tree & NU BOP. POOH w/ tbg.
2. RU WL. RIH w/ 5-1/2" CIBP & set @ 11625'.
3. RIH w/ WL guide, 10' sub, F nipple, 1 jt 2-3/8", 1X pkr, on/off tool, & 2-3/8", 4.7#, N-80 tbg to 11,450'. Pickle tbg w/ 500 gals 15% NEFE. Circ 2% KCL w/ oxygen scavenger to fill hole.
4. Set pkr. ND BOP & NU tree.
5. Swab well down to 10,000'.
6. RU Baker. RIH w/ 11/16" perf gun & perf Morrow @ 11565-11576' & 11514-11520' w/ 4 SPF (70 shots total).
7. Swab well. RDMO PU. Evaluate for additional stimulation.

RECEIVED  
OCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Analyst

DATE 07-21-99

TYPE OR PRINT NAME Terri Stathem

TELEPHONE NO. 915-683-7443

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: