

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30015-29583
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name BERETTA '15' STATE COM
Well No. 2
Pool name or Wildcat CARLSBAD MORROW SOUTH

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
Name of Operator CONCHO RESOURCES INC.	
Address of Operator 110 W LOUISIANA, STE 410, MIDLAND TX 79701	
Well Location Unit Letter <u>G</u> : <u>2180</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>23S</u> Range <u>26E</u> NMPM <u>EDDY</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3317' GR	

11

### Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ADD ADDITIONAL PAY ☒

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO ADD ADDITIONAL MORROW PAY IN THE BERETTA '15' STATE COM #2 ACCORDING TO THE FOLLOWING PROCEDURE:

1. MIRU. Kill well w/ 2% KCL water. ND tree & NU BOP. POOH w/ tbg.
2. RU WL. RIH w/ 5-1/2" CIBP and set @ 11,625'.
3. RIH w/ WL guide, 10' SUB, F nipple, 1 jt 2-3/8", 1-X pkr, on/off tool, & 2-3/8" 4.7#, N-80 tbg to 11,450'. Pickle tbg w/ 500 gals 15% NEFE. Circ 2% KCL w/ oxygen scavenger to fill hole.
4. Set pkr ND BOP & NU tree.
5. Swab well down to 10,000'.
6. RU Baker WL. RIH w/ 1 11/16" Predator gun & perf Morrow w/ 4 SPF from 11565-76' & 11514-20' (70 shots total).
7. Swab well to kick off. RDMO PU. Evaluate for additional stimulation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 06-28-99

TYPE OR PRINT NAME Terri Stathem TELEPHONE NO. 915-683-7443

(This space for State Use)

APPROVED BY Jim W. Bunn TITLE District Supervisor DATE 7-1-99

CONDITIONS OF APPROVAL, IF ANY: