Submit 3 Copies
to Appropriate
District Office

Form	C-103
Revise	ed 1-1-89

State of New Mexico	Form C-103
Minerals and Natural Resources Department	Revised 1-1-

to Appropriate	Energy, Minerals and Natura			Revised 1-	1-89	
District Office DISTRICT I	OIL CONSERVATI	on division	WELL API NO.		<u>_</u>	
P.O. Box 1980, Hobbs NM 88240	P.O. Box	2088	30-	-015-29691	!	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Le	STATE X	FEE 🗆	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	0 ()	L COM. DIV.	6. State Oil & Gas Lea	ase No.		
SUNDRY NOT	ICES AND REPORTS ON WI	ELLS COTT				
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVED (FORM C	OPOSALS TO DRILL OR TO DEEPE RVOIR. USE "APPLICATION FOR F -101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A PERMIT"	7. Lease Name or Uni Spud "16" St			
1. Type of Well: OIL GAS WELL X WELL	OTHER					
2. Name of Operator		8. Well No.				
Santa Fe Energy Resource	y Resources, Inc.			9 Pool name or Wildcat		
3. Address of Operator 550 W. Texas, Suite 133	80, Midland, TX 7970		Wildcat Lag	guna Salado) (BS)	
4. Well Location Unit Letter P : 760	Feet From The Sout	Line and 33	Feet From T1	_{he} East	Line	
Section 16	Township 23S	Range 29E	NMPM E	<u>lddy</u>	County	
	10. Elevation (Show wh	nether DF, RKB, RT, GR, etc. 2961				
11. Check A	ppropriate Box to Indica	te Nature of Notice,	Report, or Oth	ner Data		
	NTENTION TO:	SUE	SEQUENT R	EPORT O	=:	
	PLUG AND ABANDON	REMEDIAL WORK	☐ AL	TERING CASING		
PERFORM REMEDIAL WORK	_	_	COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT			
TEMPORARILY ABANDON	CHANGE PLANS L	i	CASING TEST AND CEMENT JOB			
PULL OR ALTER CASING	_	T CASING TEST AND OR			Γ	
OTHER:		OTHER:				
12. Describe Proposed or Completed Opwork) SEE RULE 1103.	perations (Clearly state all pertinen	t details, and give pertinent da	ites, including estimated	d date of starting a	iny proposed	
7/23/97: Spud 17-1/2"	hole at 6:30 p.m. [rlg.				
7/24/97: TD 17-1/2" h and set shoe at 356'. pps Flocele. Circulat on head. Test weld to Tag hard cmt at 280'.	ed 20 sx to pit. Plu 500 psi, ok. NU BOF WOC.	ug down at 2:30 a. P. Test BOP to 50	.m. WOC. Cut 00#, ok. WOC.	3.0# H-40 S 200 sx cont c casing of PU BHA a	F&C casir ained 1/4 f and wel nd TIH.	
7/25/97: WOC total of	25 hours. Resume dr	rilling operations	.			
I hereby certify that the information above i	$\alpha / (1 \wedge 1)$	wledge and belief.	an Clank	NATE 7/28/	/ 0 7	
SIGNATURE IN THE	te allough	тпиE <u>Sr. Producti</u>				
TYPE OR PRINT NAME Terry McCu	l]ough		TE	ELEPHONE NO.915/	<u> </u>	
(This space for State Use)				AUG !	5 1007	
	IGNED BY TIM W. GUM SUPERVISOR	TITLE		DATE		