## - 3.000 phi Working Pressure

J HWP

43.	::am		Min. 1.D.	Min. Nominal
1	Flowline		1	
2	rfill up line		i	2*
3	Orilling nisple			
5	Two single or one dual hydraulically ocerated rams			
6a	Orilling speel with 2° min. kill line and 3° min choke line outlets			
55	2" min, kill line and 3" min, choke line outlets in ram. (Alternate to 6a above.)			
7	Vaive	Gate 🗆 Plug 🗆	3-1/8*	
8	Gate valve-power operated		3-1/8*	
9	Line to choke manifold		1	3.
10	Valves	Gate C Plug C	2-1/16*	
11	Check valva		2.1/18*	
:2	Casing head		1	
13	Vaive	Gate Cl Plug Cl	1-12/16*	
14	Pressure gauge with need	le valve		1
15	Kill line to rig mud pump n	nanilold		2*

CTUCK CTOURCEURS



OPTIONAL				
16 Flanged valve	1-13/16"			

CONTRACTOR'S OPTION TO FURNISH:

- All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psl. minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closedagainst full rated working pressure.
- 3.80P controls, to be located near drillers position.
- 4.Kelly equipped with Kelly cock.
- 5.Inside blowout prevventer or its equivalent on demick floor at all times with proper threads to fit pipe being used.
- 8.Kally saver-sub equipped with rubber casing protector at all times.
- 7.Plug type blowout preventar taster.
- Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.
- HEC TO FURNISH:
- 1. Bradenhead or casinghead and side valves.
- 2.Wear bushing, if required.

## GENERAL NOTES:

- 1.Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- 2.All connections, valves, fittings; piping, etc., subject to well or pump pressure
- must be flanged (suitable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through chore.
- Valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position.
- 4.Chokes will be positioned so as not to hamper or delay changing of choke beans. Replaceable parts for adjustable choke, other bean sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- 5.All valves to be equipped with handwheels or handles ready for immediate use.
- 6. Choke lines must be suitably anchored.

7.Handwheels and extansions to be connected and ready for use.

- Valves adjacent to drilling speel to be kept open. Use outside valves except for emergency.
- 9.All seamless steel control piping (3000
- psi working pressure) to have flaxible joints to avoid stress. Hoses will be permitted.
- 10.Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine fill-up operations.

Exhibit 1