State of New Mexico Energy, Minerals and Natural Resources Department

=131 W	Form (
· //	

CISI	Form C-103 Revised 1-1-89
API NO.	

District Office			• //	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	ONSERVATIO P.O. Box 2088		WELL API NO.	
P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088			30-015-30757	
P.O. Drawer DD, Artesia, NM 88210	J. 33	101179	5. Indicate Type of Lesse STATE K FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	• • • • • • • • • • • • • • • • • • •	A	6. State Oil & Gas Lesse No. V-4858	
SUNDRY NOTICES AND	REPORTS ON WELL	s a		
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE (FORM C-101) FOR SI	DRILL OR TO DEEPRING "APPLICATION FOR PER	NO DELLO DACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Off. GAS WELL X	onex (Co.,		Opuntia Draw ATG State Com	
2. Name of Operator V YATES PETROLEUM CORPORATION			8. Well No.	
3. Address of Operator			9. Pool name or Wildon	
105 South 4th St., Artesia, N	88210		Und. Baldridge Canyon Morrow	
4. Well Location				
Unit Letter M : 1090 Feet Pro	The South	Line and660	Feet From The West Line	
Section 29 Townshi	23S Ram	_{me} 25E 1	NMPM Eddy County	
). Elevation (Show whether D	F, RKB, RT, GR, etc.)	WILLIAM STATE OF THE STATE OF T	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
		· ·	•	
NOTICE OF INTENTION	10:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG.	AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANG	SE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	OR ALTER CASING CASING TEST AND CEMENT JOB		MENT JOB 🗌	
OTHER:	□	OTHER: Intermedi	ate casing & cement KX	
cement at 1300'. Ran 1" and CaC12. PD 11:00 PM 10-30-99. 35 sacks "C" with 4% CaC12. at 1126'. Spotted 35 sacks "Ran 1". Tagged cement at 102 10-31-99. WOC 3 hours and 15 25 sacks "C" with 4% CaC12.	AM 10-30-99, In lar guide shoe set (yield 1.52) (yield 1.95, we ight 14.8). PD. WOC 6 hours. tagged cement at WOC 2 hours. PD 1:15 AM 10-32 C" with 4% CaCl 29'. Spotted 55 minutes. WOC. PD 9:00 AM 10-33 sacks "C" with 4% sacks "	Ran 56 joints of set at 2510'. Weight 14.6) ight 12.5). Ta 3:15 PM 10-30-Ran Temperatut 1314'. Spott Ran 1". Tagge 1-99. WOC 2 ho 2. PD 3:15 AM sacks "C" with Ran 1". Tagg 1-99. WOC 5-1/4% CaC12. PD 3	f 8-5/8" 24# J-55 (2515') Float collar set at 2465'. and 600 sacks 65-35 Poz "C", iled in with 200 sacks "C" 99. Bumped plug to 900 psi, re Survey and found top of ed 35 sacks "C" with 4% d cement at 1226'. Spotted urs. Ran 1". Tagged cement 10-31-99. WOC 2 hours. 4% CaCl2. PD 5:30 AM ed cement at 1029'. Spotted 2 hours. Ran 1". Tagged :00 PM 10-31-99. WOC 1-1/2 INUED ON NEXT PAGE:	
(This space for State Use) (This space for State Use) (This space for State Use)				

DISTRICT II SUPERVISOR