

2/15/00 10:50 A.M.

Joe Flemming w/OXY called and updated well situation on OXYs' ' Beretta 9Y State #1Y by airport Sec. 9, T23S R26E Unit K.

Cemented 7" casing to surface. TD of 7" casing is @ 9970'. Had opened up DV tool and was unable to circulate cement w/330 # of lift. Pumped an estimated 1600 sxs. Plans are to run Bond Log and determine exactly where cement runs through interval. Has TOC est. to be tied back to 1500'. Mentioned a # of thief zones in well taking fluid and drlg. mud. In pumping cement, found a barite bridge that actually blocked the flow of gas that was coming from the Strawn gas zone. This helped well control situation. Current plans are to NU & 7 16" stack and weld on to WH, PU Bit and clean down to Strawn. Deepen well to Morrow which will be @ 12,200'. Had situation well under control with 10 safety personnel out on location. Boots N/Coots among other specialist.