Submit 3 Copies to Appropriate District Office	State of Ne Er , Minerals and Natur	w Mexico ral Resources Department	cist	Form C- Revised	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA 2040 Pachecc Santa Fe, M	St. Charles	WELL API NO. 30-015-30904		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa i e, i Ni		sindicate Type of Lea	[]	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		OCD ECEIVED	state Oil & Gas Lea	STATE	FEE
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON N POSALS TO DRILL OR TO DEE VOIR. USE "APPLICATION FOI 101) FOR SUCH PROPOSALS.)	R PERMOR PLUG BACK TO A	ALease Name or Unit Harroun 15	Agreement Name	
₁Type of Weil: OlL GAS WELL X / WELL	OTHER				
₂Name of Operator Pogo Producing Company	<u>co</u> ?		₀Well No. 10		
₃Address of Operator P. O. Box 10340, Midland, TX 7970	02-7340		Pool name or Wildca Cedar Canyon		
•Well Location Unit Letter <u>K</u> : <u>1700</u>	Feet From The South	Line and 2310	Feet From The	West	Line
Section 15	Township 24S	Range 29E	NMPM	Eddy o	County
	10Elevation (Show whether 2920' GR	er DF, RKB, RT, GR, etc.)			
11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON	CHANGE PLANS		PNS.		
PULL OR ALTER CASING		CASING TEST AND CEME			
OTHER:		OTHER:		<u> </u>	
¹² Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
Spud & Set Surface Csg - MIRU TMBR/Sharp rig #14. Spud well @ 2100 hrs CST 01/26/00. Drid 14-3/4" hole to 593'. TD reached @ 2300 hrs CST 01/27/00. Ran 17 jts 10-3/4" 40.50# J-55 ST&C & Buttress csg. TPGS @ 593'. IFV @ 547'. BJ cmt'd w/ 390 sxs 65:35 POZ "C" @ 12.8 ppg followed by 150 sxs CI "C" + 2% CaCl2 @ 14.8 ppg. Circ 104 sxs. Plug down @ 1030 hrs CST 01/28/00. WOC 32-1/2 hrs. Weld on WH. NU BOP's and test to 1500 psig.					
Intermediate Csg - Drld 9-7/8" hole t @ 2875'. Float collar @ 2830'. BJ c 150 sxs. Drop plug & displace cmt.	mt'd w/ 750 sxs 65:35 POZ "(C" @ 12.4 ppg followed by 1	50 sxs CI "C" + 19	6 CaCl2 @ 14 8 n	na Circ
TD & Production Csg - Drld 6-3/4" hd 11.60# J-55 LT&C csg. Float shoe (.3% CD 32 + .15% SMS + .1% R3 @ .1% R3 @ 15.7 ppg. Lost returns la BOP's and make cut-off. Weld on W	@ 6880'. Float collar @ 6834) 15.7 ppg. Circ 100 sxs. Crr st 20 bbls. Est cmt top @ 230	'. DV tool @ 5497'. BJ cmt' t'd 2nd stage w/ 840 sxs Cl	d 1st stage w/ 275 "H" + .3% CD32 +	sxs CI "H" + .3%	FL52 +
I hereby certify that the information above is to	rue and complete to the best of my kr	outodas and belief			
SIGNATURE (athy	ember!	TITLE Operation Tech		DATE 02-28-0	0
TYPE OR PRINT NAME Cathy Tomberlin				TELEPHONE NO. 915-	-685-8100
(This space for State Use)		0.4.			
APPROVED BY	in W. Sum		Septense	DATE 3-2-	Ce
CONDITIONS OF APPROVAL, IF ANY:					