State of New Mexico

Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St. 30-015-31589 **DISTRICT II** Santa Fe, NM 87505 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.) **OXY Boo State** 1. Type of Well: OIL WELL **OTHER** 2. Name of Operator 8. Well No. RECEIVED OXY USA WIP Limited Partnershi 3. Address of Operator Pool name or Wildcat P.O. Box 50250 Midland, Undsq.Carlsbad Morrow, 4. Well Location 1980 North Feet From The Line and Feet From The Line Township **23**S Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB X OTHER: OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE OTHER SIDE

I hereby certify that the information above is true and complete to the best	of my knowledge and belief.		
SIGNATURE STATE	ππε Sr. Regulatory Analyst	DATE	2/14/02
TYPE OR PRINT NAME David Stewart		TELEPHONE NO.	915-685-5717
ORIGINAL SIGNED BY T	IM W. GUM	FE	B 2 0 2002
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	

ATTACHMENT C-103 - OXY BOO STATE #1

the second secon

12/15/01 CMIC:MIIKE LOVE

DRILLING TO 9748, TD 8 3/4" HOLE AT 2:00 PM, 12-14-01. CONDITION MUD AND SHORT TRIP 10 STANDS. TIH AND CIRCULATED BOTTOMS UP AND CHECKED FOR FLOW. TOH FOR LOGS. TIGHT SPOT AT 8330 TO 8295, (35 FT).

The second secon

12/16/2001 CMIC:MIIKE LOVE

COMPLETED TOH FOR LOGS. MIRU BAKER ATLAS AND LOGGED WELL WITH ONE RUN. TIH WITH BIT AND CIRCULATED AND CONDITION MUD. MIRU WEATHERFORD LD MACHINE AND TOH LDDP. WORKING THROUGH TIGHT SPOT AT 6757 AT REPORT TIME.

12/17/2001 CMIC:MIKE LOVE

WORKED PIPE THROUGH TIGHT HOLE AT 6757 TO 5176. LDDP AT REPORT TIME WITH NO PROBLEMS. PREP TO RUN 7" CSG THIS AM.

12/18/2001 CMIC:MIKE LOVE

COMPLETED LDDP AND DC. MIRU WEATHERFORD CASING CREW AND TIH WITH FS, 1 JT, FC AND 221 JTS OF 7" 26# L-80 LTC TO 9748. MIRU BJ SERVICES AND CEMENTED CASING WITH 675 SX 35/65 POZ FB 200 SX SUPER C MOD, PLUG DOWN AT 2:30 AM, 12-18-01, EST TOC AT 4500. NOTIFIED JERRY WITH NMOCD AT 11:15 AM, 12-17-01. ND BOP AND SET SLIPS AT REPORT TIME.

12/19/2001 CMIC:MIKE LOVE

MIRU MONAHANS NU AND SET OUT 5000# BOP AND NU 10000# BOP. CHANGE OUT AND SET IN 10000# MANIFOLD. MIRU MONAHANS NU AND TESTED TO 10000#. NIPPLE UP FLOW LINE AT REPORT TIME.

12/20/2001 CMIC:MIKE LOVE

COMPLETED NU FLOW LINE. MIRU WEATHERFORD LD MACHINE AND TIH WITH DCS AND DP. DRILLED 30' OF CEMENT TO 9738. CIRCULATED BOTTOMS UP AND JET AND CLEAN PITS AT REPORT TIME.

12/21/2001 CMIC:MIKE LOVE

COMPLETED CLEANING PITS AND FILLED WITH XCD MUD, DISPLACED WELL WITH MUD. DRILLED SHOE AND 10' OF NEW FORMATION. MIRU BJ SERVICES AND TESTED SHOE TO 13# EMW. DRILLING AHEAD AT REPORT TIME WITH NO PROBLEMS.

12/22/2001 CMIC: MIKE ELMORE

DRILLING, SURVEY, DRILLING.

12/23/2001 CMIC:MIKE ELMORE

DRILLING, BOP DRILL & SLOW PUMP RATE, DRILLING.

12/24/2001 CMIC:MIKE ELMORE

DRILLING, SURVEY-MISRUN, DRILLING, SURVEY, PUMP TOTCO & BAR SLUG, TRIP FOR BIT. 12/25/2001 CMIC:MIKE ELMORE

SI FOR CHRISTMAS.

12/26/2001 CMIC:MIKE ELMORE

SI FOR CHRISTMAS, TIH.

12/27/2001 CMIC:MIKE ELMORE

CUT DRLG LINE, TIH, WASH AND REAM, DRILLING, CHECK FLOW, SI CHECK SIDPP & SICP, DRILLING TO 10406', CIRC OUT GAS ON CHOKE, SI BRING UP MUD WT TO 10.4PPG, CIRC OUT KWM, CHECK FLOW, CHANGE OUT ROTATING HEAD RUBBER. 12/28/2001 CMIC:MIKE ELMORE

CHANGE OUT ROTATING HEAD RUBBER, DRILLING, SURVEY, DRILLING.

12/29/2001 CMIC:MIKE ELMORE

DRILLING, BOP DRILL & SPR, DRILLING TO 10690, CHECK FOR FLOW, PUMP TOTCO, TRIP FOR BIT TO 4429' WELL STARTED TO FLOW, SI, CIRC OUT WITH 10.5 PPG, TIH 6 STDS TO 4974', SI, TRY TO CIRC OUT GAS WITH 10.5 PPG, NO LUCK, SI, GET PSI, BRING MUD UP TO 11 PPG AND RIG UP BJ AND WAIT FOR DAYLIGHT TO TRY PUMPING KILL.

Some of the section o