		-	015/
Submit 3 copies	State of I	Now Mayiga	C1 / +
to Appropriate	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103
District Office	Energy, Minerals and Natural Resources Department		()   Revised 1-1-89
,			V
DISTRICT I	OIL CONSERVAT	ION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-015-31605
DISTRICT II	Santa Fe, New Mexico 87504 -2088		5. Indicate Type of Lease
P.O. Drawer DD. Artesia, NM 88210	Santa I e, Ivew Mexico	87304 -2086	
DISTRICT III DED ARTESIA			STATE X FEE  6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			V-2705
	V NOTICES AND DEPOR	PS ON HUBI I C	7-2703
	RY NOTICES AND REPORTS ON WELLS		
	R PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
	RESERVOIR. USE "APPLICATION FOR PERMIT"		Graham AKB State
	RM C-101) FOR SUCH PROPOSA	LS.)	
1. Type of Well:			
OIL GAS			
Well Well 2. Name of Operator	OTHER		
Yates Petroleum Corporation			8. Well No.
3. Address of Operator	-		9. Pool name or Wildcat
105 S. 4th Street, Artesia, NM 88210			Undesignated Lost Tank Delaware
4. Well Location			
Unit Letter G: 1.980	Feet From The <u>North</u>	Line and1,650	Feet From The East Line
Section 2	Township 22S	Range 31E NMPM	Eddy County
			Eddy County
		536 GR	
11. Che	eck Appropriate Box to Indi	cate Nature of Notice, Report,	or Other Data
NOTICE OF IN	NTENTION TO:		ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	_
	LUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CACING TEST AND CEMENT	s von 🗀
		CASING TEST AND CEMENT	JOR [
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.  Yates Petroleum Corp. respectfully requests permission to change the setting depth of the 13 3/8" casing from 650' to 850'. This is still prior to casing the salt but will			
case off the portion of the Ruslter Anhydrite that generally can cause hole problems in this area.			
•	g tun tune note problems	in tins area.	
Thanks you,			
,			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Cory treplens	TITLE Drilling F	Ingineer Asst	1/22/24
— <del>—                                  </del>	THE DINNING P	Ingineer Asst. DATE	1/22/01
TYPE OR PRINT NAME Cory Frederick			TELEPHONE NO.(505)-748-4214
(This space for State Use)			
- /			
APPROVED BY MILL STUDY IS	TITLE FICIO	Rea IT	- hul-on
	TITLE PICTO	DATE _	3 14 2001
CONDITIONS OF APPROVAL, IF ANY:			