Form 3160-5 (June 1990)

(This space for Pederal or State office use)

Conditions of approval, if any:

to any matter within its jurisdiction

Approved by

UNTED STATES DEPARTME. . OF THE INTERIOR

C15 10

N.M. Oil Cons. Division Over 1004-0135 **BUREAU OF LAND MANAGEMENT** 1625 N. French Bores March 31, 1993 Parties of the Property of SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different relabbs, NMN88240 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation Type of Well ☐ Gas Well ⊠ Oil Well Other 8. Well Name and No. 2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP. Todd "13F" Federal # 27 9. API Well No. 3. Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMÁ-73102 (405) 235-36 30-015-31879 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage. Sec., T., R., M., or Survey Description) 1997E Ingle Wells-Delaware 1980' FNL & 1930' FWL, Sect 13-23S-31E, Unit "F" 11. County or Parish, State Eddy County, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent **New Construction** Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water Other Perf & Acidize : Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Devon Energy Production Company, L.P. plans to perforate and Frac middle Brushy Canyon Zone & Add upper Brushy & Cherry Canyon pay as follows: TOH w/rods & pump. ND WH & NU BOP. POOH w/tbg. RIH w/RBP, pkr, & tbg to 7700'. Set RBP & test to 3000 psi. PU to 7350' & set pkr. Frac zone down tbg w/28,000# of 16/30 Ottawa, flow well back, until well dies. Rel pkr. & POOH w/tbg & pkr. MIRU WL. RIH w/4" csg gun & perf Delaware @ 7100'20' (2 SPF, 40 shots) & 6114-27' (26 shots). RD WL. RIH w/pkr & tbg to RBP @ 7700'. Reverse off sand & rel RBP. PU to 7300' & reset RBP & test to 3000 psi. Acidize zone w/1500 gal 7.5% NEFe acid. Swab. Reset pkr @ 6100'. Frac zone down tbg w/45,000# of 16/30 Ottawa. Rel RBP. PU to 6100' & reset RBP test to 3000 psi. Acidize zone w/1500 gal 7.5% NEFe acid. Swab. Frac zone down tbg w/45,000# of 16/30 Ottawa. RIH w/40 jts $\frac{1}{2}$ 7/8" 6.5# N-80 tbg to 83 $\overline{7}$ 0'. Hang well on to pump. 14. I hereby certify that the foregoing is true and correct Karen A. Cottom Date May 13, 2002

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as

Engineering Technician

Date