Additional Operator Remarks:

Surface casing to be set = - 100' above the Salt.

Production casing cement will be brought up at least 500' above the upmost hydrocarbon bearing zone.

Drilling procedure, BOPE diagram, Anticipated Formation Tops, and Surface Use Plans attached.

This well is located inside the R-111 Potash Area and inside the Secretary's Potash order, but in the barren area for potash.

There are no potash leases within 1 mile of this location.