Submit 3 Copies to Appropriate District Office P.O. Box 1980, Hobbs, NM, 48240 District of New Mexico Linerals and Natural Resources Department CIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206	CIST Form C-103 Revised 1-1-89		
P.O. Box 1980 Hobbs, NM 4240 DISTRICT II SID Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503	Well. API NO. 30-015-32286		
DISTRICT II P.O. Drawer DD, Artenia, NDA 38210 DISTRICT III	5. Indicate Type of Lasse STATE FEE		
1000 Rio Brizer Rd., Azzer NIM 87410	6. State Oil & Gas Lesse No. Fee		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Echols Com		
1. Type of Well: OL GAS WELL C OTHER			
2. Name of Operator	8. Well No.		
Gruy Petroleum Management Co. 3. Address of Operator	2 9. Pool name or Wildcat		
P. O. Box 140907, Irving TX 75014-0907	White City; Penn (Gas)		
Section 12 Township 23S Range 26E	Feet From The East WEST Line		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3258' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			
PULL OR ALTER CASING CASING TEST AND CEN			
OTHER: OTHER: OTHER:	& Intermediate Casing		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclus work) SEE RULE 1103. 11/13/02 Spuid well Drill to 487' and ran 11 its of 13 3/8" 48 H40STC cossing Ci			

11/13/02	Spuu weii. Diii to 467 anu fan 11 jts. of 15 5/6 46	H4051C casing.	Circulate casing and RU Halliburton.
	Cement with 340 sx of lead & 150 sx of tail cement.	Circulate 120 sx	c to pit.

11/26/02 Drill to 3188'. RU casing crew and 71 jts of 9.625/40/J/STC casing. Circulate and cement with 1100 sx of lead and 200 sx of tail cement.

11/27/02 Circulated 180 sx to reserve pit.

See Attached Drilling Report

I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	mate Production Assistant Pare
TYPE OR PRINT NAME Natalie Krueger	тецерноме но. 972-401-3111
(This space for State Use) APPROVED BY FOR NECOAD with BU CONDITIONS OF APPROVAL, IF ANY:	DEC 0 9 2002

## Gruy Petroleum Management Co.

Magnum Hunter Production, Inc.

## Well History

November 14, 2002 Thru December 2, 2002

## **OPERATED**

## **CARLSBAD SOUTH**

	TROLEUM MA	ANAGEMENT CO #2	W.I. Pct BCP W.I. Pct ACP	22.50 % 22.50 %
EDDY, N		Sec 12, T23S, R26E		orrow / 0'
11/14/2002		Depth 487	1440	1100 / 0
		Progress 487		
AFE:	22091	Present Operation: NU BOP Stack		
ML.	22071	Spud well & drill to 277'; WLS @ 230' = .75 degs; drlg to 487'; CIRC sweep aro	und; drop survey too	1&
		trip out of hole, laydown ramer & shock sub; RU casers & run 11 jts of 13-3/8" 4 487'; CIRC casing; RU Hall & cmt w/340 sx of lead & 150 sx of tail cmt, CIRC	120 sx to pit; WOC;	cut
		conductor & casing; dress casing, heat wellhead & weld on, test wellhead to 500 stack.	#, good tet; NU BOP	
11/15/2002		Depth 1,450 Progress 963		
AFE:	22091	Present Operation: Drlg		
		Nipple up BOP stack. Test blinds to 500 psi. Trip in hole with BHA. Drill cemer cement to 465'. Test pipe rams and annular to 500 psi. Drill cement and guide sh new formation to 965'. 30-55K WOB/65 RPM. Wireline Survey at 920' - 1.25 de - 1375'. 35 - 50 WOB/65 RPM. Wireline Survey at 1329' - 1.75 degrees. Drilling 30K WOB/65 RPM.	be at 487'. Drilling grees. Drilling from	965'
11/16/2002		Depth 1,662		
		Progress 212		
AFE:	22091	Present Operation: WO Cement Plug		
		Drilling from 1450' - 1662' w/ one pump. Working on pump # 1. Ran wireline su twice and found chart inside tool. Ran third time w/ same results. Ran 7 degree to degree tool from Hobbs, NM. Trip out of hole and check crow's foot. Installed pr Trip in hole to 1322'. Having no hole problems associated with deviated hole. Ra up to casing shoe and found angle at 1322' was 6.5 degrees and at casing shoe w BHA. Pickup drill pipe to 921' and ordered 220 sx of cement for plugback. Wait Halliburton and pump 220 sx balanced plug from 921' to 600'. Good action on pl and laydown remainder of pipe in hole. Wait on cement to set.	ool off another rig. W operly. Laydown bot n 14 degree tool on e as 1.25 degrees. Stan on Halliburton. Rig u	/ait on 14 tom IBS. every stand idback 1p
11/17/2002		Depth 674 Progress 0		
AFE:	22091	Present Operation: Time Drlg at 2 min/inch		
		Wait on cement and pick up BHA. Tag cement at 612' and dress off to 643' when drilling at 2 - 2.5 min/inch. Saw approximately 40% formation at 655' and presen 80% cement.		
11/18/2002		Depth 0		
		Progress 0		
AFE:	22091	Present Operation: TIH Open-Ended		
Monday 2 I	December 2002	Drilling cement plug from 674' - 799'. Samples show decrease in formation and 1		

¢	survey at 749' - 1.5 degrees. Drilling cement from 799 - 880' with 5K WOB. Cement getting softer in salt section below 750'. W <sup>2</sup> is survey at 880' - 1.75 degrees. Drilling from $\gamma'$ - 955'. Fell out of cement at 955' and lower bit to 1020'. Noag or bridges in hole. Wireline survey at 948' degrees. Trip out of hole to pick up monel DC to run directional surveys. Pick up drill pipe for second cement plug. Ordered 220 sx of Premium cement and directional tools. Wait on monel DC and single shot tool. Make up bit, bit sub, monel DC, and remainder of BHA and trip in hole to 1380'. Circulate hole clean for surveys. Run single shot directional surveys at 1380' - 6.5 deg at N80E, 1190' - MR, 1000' - 3.5 deg at N71E, 810' - 2 deg at N50E, 620' - 1.25 deg at N19E, and 525' - 1.25 deg at N18E. Standback BHA. Trip in hole with open ended drill pipe for cement plug from 760' - 450'.
11/19/2002	Depth 0 Progress 0
AFE: 22091	Present Operation: WOC Trip in hole with open ended drill pipe to 755'. Pump 220 sx of Premium cement with 3% Calcium chloride and balance from 755' - 450' as calcu- lated. Weight of cement was 15.1 ppg. Wait on cement. Laydown 12 jts of drill pipe, put up windwalls around floor, and pick up BHA to drill cement. Unloaded SDI directional equipment.
	Surface samples of cement fairly hard after 8 hrs. Tag up cement at 487' and drill cement to 524' with 5 - 10K WOB at 36 - 40 seconds per foot. Circu- lated samples up and cement was still green. Wait on cement and pick up swivel for wireline operations. Drill 16' of cement from 524' - 540' with 15K WOB and 46 RPM. Drilled at 30 seconds per foot. Cir- culated samples up and cement still too green to sidetrack. Halliburton suggested waiting full 24 hrs before attempting to drill out. Wait on cement. Surface samples very hard.
11/20/2002	Depth602Progress62
AFE: 22091	Present Operation: Time Drilling
	Dress cement from 540' - 578' drilling at 40 - 47 sec/ft. Cement getting firmer. Pull up into casing and circulate while waiting on cement to harden. Trip out of hole for BHA change. Change bend on motor sub from 2.12 degree to 2.6 degree. Trip in hole to shoe at 487'. Set up wireline equipment and orient tool face at 195 degrees. Sliding at 1'/hr from 578' - 588'. Samples showed up to 10% formation to 583' then decreased to 1 - 2%. Began sliding at 3 min/inch and samples came up to 20% formation at report time.
11/21/2002	Depth 926 Progress 0
AFE: 22091	Present Operation: Time Drill Open Hole Kickoff
	Time drilling from 602' to 628', cmt starting to get mushy & formation content getting less, drilling thru cmt with 4-6K WOB looking for hard cmt, fell out of cmt completely at 748'; TIH to 919; orient toolface; time drilling from 919' to 925' at one inch per 5 mins, action of string indicates possible trying to kickoff and samples are 100% salt crystals, worked groove in well from 875' to 919' before starting time drilling.
11/22/2002	Depth 955 Progress 33
AFE: 22091	Present Operation: Slide Drilling 3 min/inch
	Time Drilling from 925' - 934' at 5 min/inch getting 95% Salt and 5% Cement. Increase time drilling from 5 min/inch to 3 min/inch. Samples 100% Salt with trace of cement. Presently at 955' and approximately 12" away from old wellbore.
11/23/2002	Depth 1,233 Progress 278
AFE: 22091	Progress 278 Present Operation: Drilling
	Slide drilling from 955' - 963' at 3 min/inch. Slide drilling from 963' - 1046' with 2K WOB. Survey at 963' was 1.4 deg at 81.8 Az. Rotate from 1046' - 1110' with 12K WOB. Survey at 1069' - 1.9 deg at 189.4 Az. Short trip above KOP and trip back in to bottom with no problems. Laydown 14 jts of drill pipe. Trip out of hole and laydown directional tools and change swivels. Pickup BHA and TIH to 1110' with no problem going through KOP. Drill from 1110' - 1138'. Run wireline survey at 1058' - 1.25 degrees. Directional tools had shown 1.8 degrees around same depth. Drilling from 1138' - 1223' with 25 - 30K WOB.