
Form 9-881 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bursan No. 42-P258.4. Approval-expires 12-31-4C. Land Office. Sauta Fe.
Land Office Santa Fe
Lease Nov. 1.007073
Unit H
Oli Cons. Commis

1	ENTION TO DRILL		UENT REPORT OF WATE		4
1	ENTION TO CHANGE PLANS	!		TING OR ACIDIZING	1
1	ENTION TO TEST WATER SHUT-OFF.			RING CASING	1
	ENTION TO RE-DRILL OR REPAIR W	: }		RILLING OR REPAIR	I V
	ENTION TO SHOOT OR ACIDIZE	. 1		DONMENT	
t	TENTION TO PULL OR ALTER CASING				1
NOTICE OF IN	ENTION TO ADMITTOR WELL				
	(INDICATE ABOVE BY	CHECK MARK NATURE OF F	EPORT, NOTICE, OR OTH	ER DATA)	
30-	14160-216			July 30,	, 19.5
	1 is located 2310 K/4 Sec. 1 T-26 and Sec. No.) (Tw)	•		from $\left\{ egin{array}{c} \mathbf{E} \\ \blacksquare \end{array} \right\}$ line of \mathbf{E}	sec1
Wildcat		Rddy (County or Subdivision		Wew Mexico (State or Territory)	
The elevation	on of the derrick floor abo	ove sea level is30	90. ft. VORK		ing jobs, ceme
The elevation (State names of RECORD: 8	on of the derrick floor about	DETAILS OF Tands; show sizes, weights, sints, and all other imports 3" - Set (left: 35! 1830'-5 sax cement plug - 5 sax cement	WORK Ind lengths of proposed work) In hole) Int plug - hole bridge hole plug - bridge	casings; indicate muddi le mudded to 1 -1560'=5 sax o bole at 50' =	.750
The elevation (State names of RECORD: 8 SGING RECORD)	and expected depths to objective as ing poly urface: 20 8 5/8 alt water - 1260-178: Bridged hole at 1 hole 1750' - 5 say bridge hole 930' - plug - 5' of 3" pithereon.	DETAILS OF Tands; show sizes, weights, sints, and all other imports 3" - Set (left: 1830'-5 sax cement plug - 5 sax cement plug - 5 sax cement ipe at top with	WORK Ind lengths of proposed in hole) In hole) In proposed work In hole In plug - hole bridge hole plug - bridge 2 sacks with	casings; indicate muddi le mudded to 1 -1560'-5 sax c bole at 50' - above locatio	.750° = 1 :ement pl - 2 sax (en inscr: