

Form 9-331a
(Feb. 1961)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

(SUBMIT IN TRIPLICATE)

Land Office Artesia

Lease No. LC-061581

Unit W

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

DEC 2 1960

SUNDRY NOTICES AND REPORTS ON WELLS

D. C. C.

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1 copy to S.

November 18, 19 60

Gulf-Federal Beaty

Well No. 2 is located 660 ft. from [N] line and 1980 ft. from [E] line of sec. 24

NE 1/4 of NE 1/4 Sec. 24 T-26-3 R-29-E NMPM

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Brushy Draw (Delaware) Eddy County New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2,992 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Drilled well to 3214' with cable tools. Found top black line @ 3154'. Drilled into Delaware Sand and found formation water productive. Plugged well as follows: 150' plug (3221'-3071'), 150' plug (1000'-850'), 150' plug (750'-600'), 150' plug (450'-300'), 50' plug (50'-0'). 4 1/2" pipe marker has been installed. Hole was filled with mud-laden fluid. Cement plugs were set on HOWCO plugs. Plugging has been completed, but drill site has not yet been leveled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Curtis Hankamer

Address 1422 Bank of the Southwest Bldg.

Houston 2, Texas

By Phil C. Hankamer
Title Engineer