								et Bureau No. oval expires 12	. 42-R355.4. ⊢31-60,	
Form 9-33	0						<b>U.</b> S.	. Land Off	1CEL	C
							Seri	al Numbei	R 062	546
							LEAS	SE OR PERM	ит то Рв	OSPECT
						UNI	TED STATE	SIN		
					DEPAR		T OF THE	111/11	OR	
									SEPE	
				ECE			OGICAL SURV		~~~ <b>F</b>	144 ·
				L	og of	OI	L OR G	AS V	VEL	L
LOCA	TE WELL (	CORRECTLY	<u>,</u>	. :: (117) 이 (125년)						
Company	<b>T</b> .	W.Loffle				lress 9	14 W.T.W	iggonei	Bldg.	
Lessor or	Tract	Brunson	n-Feder	ral	Fie	d . <b>W11</b>	dcat	State	New	Mexico
							Cou			
							ne of			
							ecord of the w			
		etermined f			records.				II WORK	ione thereo
					Signed	<b>]</b> ].	S.U.	29-	un	
Date	9-5-59						Title	pt-Ope	zatoz.	
The	summary	on this pa	ige is for t	the cond	ition of the	vell at	above date.			
Commen	ced drilliı	ng <b>August</b>	10,	,	19 <b>59</b> . Fi	ished	drilling8-7	22		, 19.59
			O	IL OR	GAS SAND	OR	ZONES			
					(Denoie gas by	G)				
		-					om			
No. 2, fro	)m		to		No	. 5, fro	om	to	D	
No. 3, fro	)m		to		No	. 6, fro	m	to	)	
			J	IMPOR'	TANT WAT	ER SA	ANDS			
No. 1, fre	om No	one	to		No	. 3, fro	m	to	)	
No. 2, fro	om		to		No	. 4. fro	m	ta	)	
					ASING REC	•				
Size	Weight	Threads per	Maka		Tind of all	G	t and an Rod from	Perfo	rated	
	er foot	inch Eps werts in	Make	Amoun OL R.C.O.	nt Kind of sh	1	t and pulled from #86 <del>9`issi([63`</del>	From-	To	Purpose
5/8 <u>000</u>	247	A CALL SUG I	TE OZIGET SI	296	- Chaide		e in the samue. Frankred, give	gole Non	<u>សមត្ថក</u> ្រាយ សំខេត្តក្រស់	Surfac
	ho-91-06-6	دىرىدۇرىي 1943-يىلىرىيەر 1943-يىلىرىرى	0.418.16.8.6.		مستكر غدؤ فكسام أشتابا فت	بغب المتبهد	we sigte in duta	htter vares	<u></u>	a le toxemma
			H13	IOBX (	05 517 58	ाः श्व	METT 16-			Ship and the second
			-							
••••••••••••••••••••••••••••••••••••••	1		-  <del>;</del>	-						
		······					RECORD			
	·		MUDI	DING A	ND CEMEN					ud used
Size casing	Where set	Numb	MUDE oer sacks of ce		ND CEMEN	<u> </u>	Mud gravity	Ап	nount of n	
	Where set	Numb	••••		1	<u> </u>	Mud gravity	An	nount of m	
	Where set	Numb	••••		1	<u> </u>	Mud gravity		nount of m	
	Where set	Numb	••••		1	<u> </u>	Mud gravity	An	nount of m	
	Where set	Numb	••••	ement	Method us	ed		An	nount of m	
<u>casing</u>			er sacks of ce	ement PLUG	Method us	APTE	RS			
casing	plug—Ma		er sacks of ce	ement PLUG	Method us	APTE	RS I	Depth set		
easing	plug—Ma		er sacks of ce	PLUG	Method us S AND AD Length Size	d	RS I	Depth set		
casing Heaving J Adapters-	plug—Ma —Materia		er sacks of ce	PLUG	Method us S AND AD Length Size DOTING RE		RS I	) epth set		
easing	plug—Ma		er sacks of ce	PLUG	Method us S AND AD Length Size	d	RS I	) epth set		
teasing Heaving J	plug—Ma —Materia		er sacks of ce	PLUG	Method us S AND AD Length Size DOTING RE		RS I	) epth set		
teasing Heaving j	plug—Ma —Materia		er sacks of ce	PLUG	Method us S AND AD Length Size DOTING RE		RS I	) epth set		

Rotary tools were used from \_\_\_\_\_\_ feet to \_\_\_\_\_\_ feet, and from \_\_\_\_\_\_ feet to \_\_\_\_\_\_ feet

Cable tools were used from	feet to	3553 feet, and from	feet to feet
		DATES	
,	19	Put to producing	, 19
The production for the first	24 hours was	barrels of fluid of which	% was oil;%
emulsion;% water; and	% sediment.	Gravity, °Bé	
If gas well, cu. ft. per 24 ho	urs	Gallons gasoline per 1,000 cu. ft	. of gas
Rock pressure, lbs. per sq. i	n		
	EM	PLOYEES	
	, Driller		, Driller
			, Driller

## FORMATION RECORD

FROM	то-	TOTAL FEET	FORMATION
0	700	700	Redbed- Gravel
700	1000	300	Salt-Redbed
000	1200	200	Shale
200	2300	1,100	Anhydrite
300	2600	300	Salt-Anhydrite
600	2900	300	Anhydrite
900	3200	300	Balt-Anhydrite
200	3390	190	Anhydrite
390	3439	49	Delaware Lime( Black Lime)
439	3553	114	Delaware Sand
EBF0112 -		30671° kefec	LOCK

FORMATION DEMONSTRATION

16-43094-4

## FORMATION RECORD—Continued

;	- ÷3	5

٠٢. · •

0 5 - -

÷ [? ÷₽

> - ---.....

FROM-	то—	TOTAL FEET	FORMATION
			- 1 2
		2	
1			
		4 ( L	- パイ 特徴 御職 シード・
	1.8		

16-43054-2 0. 8, GOVERNMENT PRINTING OFFICE -----

. . . . . . . . . . . . . . . .

....

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was. "Bidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.