Sem: 3160-5 November 1983)		TED STATES		SUBMIT IN TRIPLICA' (Other instruction on	PA	Expires August 5. LEASE DEBIGNATION	31, 1985	141	
(Formerly 9-331)		- LAND MANAGEM		verse side)		LC-068282-B	AND BEEIAL NO	5	
		AND REPORT			1	6. IF INDIAN, ALLOTTEE	OR TRIBE NAM	I	
(Do not use th	is form for proposals to Use "APPLICATION	o drill or to deepen or pl FOR PERMIT—" for su	lug back to ich proposa	a different reservoir. s.)		N/A			
1. OIL CAS WELL GAS WELL OTHER				MAY 18 1987		7. UNIT AGREEMENT NAME N/A			
2. NAME OF OPERATOR						8. FARM OR LEASE NAM	E		
Hanson Operating Company, Inc.				O. C. D.		HANSON FEDERAL BATTERY #1			
3. ADDRESS OF OPERATOR ARTESIA, CFFICE						9. WELL NO.			
P. O. Box 1515, Roswell, New Mexico 88202-1515						10			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						10. FIELD AND POOL, OR WILDCAT Mason Delaware, North			
Unit F, SEANWA, 2310' FNL & 1650' FWL					ſ [-	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA			
						Sec.25,T.26S,	R.31E		
14. PERMIT NO.	15.	ELEVATIONS (Show whether	er DF, RT, GI	3, etc.)	12. COUNTY OR PARISH 13. STATE				
······································		-3133' GR-	· · · · · · · · · · · · · · · · · · ·			Eddy	New Mex:	ίœ	
16.	Check Approp	oriate Box To Indicat	ie Nature	of Notice, Report, o	or Oth	ner Data			
NOTICE OF INTENTION TO :				SUBSEQUENT REPORT OF :					
TEST WATER SHUT	-OFF PULL	OR ALTER CASING		WATER SHUT-OFF		REPAIRING W			
FRACTURE TREAT	X MULTI	PLE COMPLETE		FRACTURE TREATMENT		ALTERING CA			
SHOOT OR ACIDIZE	ABAND	0N*		SHOOTING OR ACIDIZING		ABANDONMEN	T*		
REPAIR WELL	X CHANG	E PLANS		(Other)	•/				
(Other)				(Norg: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					
17. DESCRIBE PROPOSED proposed work, nent to this work.	If well is directionally	NE (Clearly state all pert drilled, give subsurface	inent deta locations a	ils, and give pertinent da nd measured and true ver	tes, in rtical	cluding estimated date depths for all markers	of starting an and zones per	iy ti-	

Propose to clean out well bore to original total depth of 4160', fracture and stimulate as needed. Return well back to production.

18. I hereby certify that the foregoing is true and correct SIGNED SIGNED	roduction Analyst	DATE _	05/06/87
(This space for Federal or State office use) APPROVED BY	10, 05 DAREA FEVERAL TITLECARLEGAD RESOURCE AN A	DATE _	9 12-87

*See Instructions on Reverse Side