

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TR CATE*
(Other Instructions on re-
verse side)

Form approved.
Budget Bureau No. 42 R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-068823-C	
2. NAME OF OPERATOR J. M. C. Ritchie ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 5521, Midland, Texas 79701		7. UNIT AGREEMENT NAME Welch	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 685' FNL & 622' FWL Unit Letter D		8. FARM OR LEASE NAME Welch Unit	
14. PERMIT NO. 30-015-24176		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3255 GL		10. FIELD AND POOL, OR WILDCAT Welch Delaware	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 21, T-26-S, R-27-D	
		12. COUNTY OR PARISH Eddy	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

December 20, 1969 - Abandoned well, pulled casing

20 sx cement plug at 2110', filled casing with 9.6# brine mixed with salt gel to make mud. Shot off 5 1/2" casing at 1695'. Spotted 20 sx cement plug at 1685' - pulled 5 1/2" casing to 1270' - spotted 20 sx plug put 5 sx cement in surface with marker.

Locations not cleaned up. Tank Battery not moved - will advise when this has been done and ready for inspection.

RECEIVED

OCT 15 1970

C. C. C.

ARTESIA, OFFICE

RECEIVED

JAN 20 1970

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 12-31-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

H. L. BEEKMA

*See Instructions on Reverse Side