

Form 9-581a  
(Feb. 1961)Budget Bureau No. 42-R358.4.  
Form Approved.

**APPROVED**  
 NOV 6 1963  
 RONNIE E. SHOOK  
 ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY

Land Office MM  
 Lease No. 05921  
 Unit 1

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

30-015-10005 August 29, 19 63  
**Superior Federal A**  
 Well No. 1 is located 330 ft. from Box line and 530 ft. from Box line of sec. 6  
S. 1 Sec. 6 26S 25E 10M  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Midcat Eddy New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to a total depth of 1103 feet and was found dry. Well plugged 8/15/63 as follows: 22 sacks cement from 900 - 1000 feet; 22 sacks from 150 - 250 feet; 16 sacks from 0 - 20 feet. Balance hole filled with mud. Steel marker is erected. When pits are leveled notification will be mailed.

RECEIVED

NOV 7 1963

D. C. C.  
 ARTESIA OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Universal Production Service, Inc.Address Box 953, Midland, TexasBy [Signature]Title Agent

